

Nokia PE Delhi NCR-21 Alarm Handling SOP for ALARM_7481

Node: Nokia-PE-Delhi-NCR-21 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_7481

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7481 on Nokia PE Delhi NCR-21, a Provider Edge Router.

Potential Root Causes

Cause	Probability
Hardware failure in the Routing Engine or Line Card	High
Configuration error or inconsistency	Medium
Software issue or bug	Low

Diagnostic Commands

```
show system resources
show chassis environment
show interfaces terse
show bgp summary
show bgp neighbors
```

Resolution Steps

- Step 1: {'Step': '1. Check system resources and chassis environment', 'Action': 'Run show system resources and show chassis environment commands to identify any hardware issues.'}
- Step 2: {'Step': '2. Verify interface configuration and status', 'Action': 'Run show interfaces terse command to identify any interface-related issues.'}
- Step 3: {'Step': '3. Check BGP configuration and neighbor status', 'Action': 'Run show bgp summary and show bgp neighbors commands to identify any BGP-related issues.'}
- Step 4: {'Step': '4. Reload the Routing Engine or Line Card', 'Action': 'Use the reload command to restart the affected component.'}
- Step 5: {'Step': '5. Verify the issue is resolved', 'Action': 'Run show system resources and show interfaces terse commands to verify the issue is resolved.'}

Post-Check Verification

```
show system resources
show interfaces terse
show bgp summary
```