Code: main.py

import random

Set the threshold values for temperature and humidity

TEMP_THRESHOLD = 85 # degrees Celsius

HUMIDITY_THRESHOLD = 45 # percent

Generate a random temperature value between 0 and 100 degrees Celsius temperature = random.uniform(0, 100)
print("Temperature:", temperature)

```
# Generate a random humidity value between 0 and 100 percent humidity = random.uniform(0, 100)
print("Humidity:", humidity)

# Check if either temperature or humidity is above the threshold if temperature > TEMP_THRESHOLD:
    print("High temperature alarm!")
if humidity > HUMIDITY_THRESHOLD:
    print("High humidity alarm!")
```

