

Safe Watchdog Manager Release Notes

Author: TTTech

Security: Confidential

Document number: D-SAFEX-RP-70-012

Document Version: 3.4.6

Date: 21.11.2014
Status: released
Review: JDU

TTTech Automotive GmbH

Schoenbrunner Str. 7, A-1040 Vienna, Austria, Tel. + 43 1 585 34 34-0, Fax +43 1 585 34 34-90, office@tttech-automotive.com

No part of the document may be reproduced or transmitted in any from or by any means, electronic or mechanical, for any purpose, without the written permission of TTTech Automotive. Company or product names mentioned in this document may be trademarks or registered trademarks of their respective companies. TTTech Automotive undertakes no further obligation in relation to this document.

Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 2

Approval

Name	Function	Signature
PPU	Project Manager	
TGA	Head of Software Department	
MAL	Quality Manager	

Revision Chart

A revision is a new edition of the document and affects all sections of this document.

Document Version	Date	Responsible Person	Modification
0.9.0	09.06.2011	PPU	Version for Series Release 0.9
0.9.1	17.06.2011	PPU	Integration with DaVinci tool chain.
1.0.0	15.07.2011	PPU	Integration with DaVinci tool chain.
1.1.0	19.08.2011	PPU	Version for Series Release 1.1
1.2.0	07.09.2011	PPU	Version 1.2.0, TMP570LS3xx related release
1.3.0	16.09.2011	PPU	Version 1.3.0, MPC56xx (MPC5604B) release
1.3.1	06.12.2011	PPU	Version 1.3.1, Wdg_MPC56xx_bswmd.arxml changed only
1.4.0	14.12.2011	PPU	New software release and document split. Watchdog Manager, Interface and Driver becomes own Release documents.
1.5.0	10.02.2012	PPU	Version 1.5.0
1.6.0	08.03.2012	PPU	Release 1.6.0
1.7.0	13.04.2012	PPU	Release 1.7.0
1.8.0	21.11.2014	PPU	Release 1.8.0
1.8.1	12.06.2012	PPU	Release 1.8.1 did not contain WdgM module. It contains the MPC56xx driver only.
1.8.2	13.07.2012	PPU	Release 1.8.2, BugFixes, Manager release only

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH





Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 3

1.9.0	07.09.2012	PPU	Release 1.9.0, Code only
1.9.1	15.09.2012	PPU	Release 1.9.1, Documentation only
1.9.2	21.09.2012	PPU	Release 1.9.2, Style sheet update
1.9.3	02.10.2012	PPU	Release 1.9.3, S-WdgM Verifier - update, S-WdgM_UserManual - document update S-WdgM_Stack_SafetyCase - document new
2.0.7	25.10.2012	PPU	Test release 2.0.7 to check the delivery structure. This is NOT a customer release!
3.0.3	16.11.2012	PPU	Cumulative module update. (The major version changed to 3 because of the API change in function (Wdglf_GetTickCounter())
3.1.0	11.01.2013	PPU	Release 1.11.0, embedded code not changed
3.1.1	27.02.2013	PPU	Release 1.13.0, Verifier update only
3.2.0	05.04.2013	JDU	Release 1.14.0, generator update only
3.3.2	29.11.2013	PPU	Release 1.21.0, generator only
3.4.0	19.02.2014	PPU	Autosar 4 update and bug fixes, beta version
3.4.1	21.03.2014	PPU	Update and bug fixes for Autosar 4 environment compatibility. Backward compatibility to Autosar 3.1 environment added too.
3.4.2	10.04.2014	PPU	Generator bug fix for Autosar compatible driver
3.4.3	27.05.2014	PPU	Release for the AUTOSAR 4.0 and AUTOSAR 3.1 compatible S-WdgM module
3.4.4	14.08.2014	PPU	Safety Case document for previous version 3.4.3 released only.
3.4.5	04.11.2014	PPU	S-WdgM Generator correction only
3.4.6	21.11.2014	PPU	S-WdgM Generator correction only

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH



Page 4

Project Name: Safe Watchdog Manager

Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes

Contents

1	Ove	rview	6
2	Con	itent of the Module Release	7
3	Cha	nge history	9
	3.1	Changes with version 3.4.6	g
	3.2	Changes with version 3.4.5	g
	3.3	Changes with version 3.4.4	10
	3.4	Changes with version 3.4.3	10
	3.5	Changes with version 3.4.2	10
	3.6	Changes with version 3.4.1	11
	3.7	Changes with version 3.4.0	11
	3.8	Changes with version 3.3.2	11
	3.9	Changes with version 3.2.0	11
	3.10	Changes with version 3.1.2	13
	3.11	Changes with version 3.1.1	13
	3.12	Changes with version 3.1.0	13
	3.13	Changes with version 3.0.3	14
	3.14	Changes with version 2.0.7	15
	3.15	Changes with TTTech Release 1.9.3: S-WdgM Subpackage 2.0.6	15
	3.16	Changes with TTTech Release 1.9.2: S-WdgM Subpackage 2.0.5	16
	3.17	Changes with Release 1.9.1: S-WdgM Subpackage 2.0.4	17
	3.18	Changes with Release 1.9.0: S-WdgM Subpackage 2.0.3	17
	3.19	Changes with Release 1.8.2: S-WdgM Subpackage 1.8.2	20
	3.20	Changes with Release 1.8.0: S-WdgM Subpackage 1.8.0	20
	3.21	Changes with Release 1.7.0: S-WdgM Subpackage 1.7.0	20
	3.22	Changes with Release 1.6.0: S-WdgM Subpackage 1.6.0	20
	3.23	Changes with Release 1.5.0: S-WdgM Subpackage 1.5.0	21
	3.24	Changes with Release 1.4.0: S-WdgM Subpackage 1.4.0	21
	3.25	Changes with Release 1.3.1: WdgM Subpackage 1.3.1	21
	3.26	Changes with Release 1.3.0	21
	3.27	Changes with Release 1.2.0: WdgM Subpackage 1.2.0	21
	3.28	Changes with Release 1.1.0: WdgM Subpackage 1.1.0	22
	3.29	Changes with Release 1.0.0: WdgM Subpackage 1.0.0	23
4	Test	t status	24
5	Kno	own issues, limitations, updates	25
6		previation and glossary	26

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH Author: TTTech

Version: 3.4.6





Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 5

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH

 Document Title:
 Release Notes
 Doc.No:
 D-SAFEX-RP-70-012
 Page 6

1 Overview

The **Safe Watchdog Manager** (**S-WdgM**) is upper software layer of the **Safe Watchdog Manager Stack**. The S-WdgM Stack is part of the service layer of the AUTOSAR architecture. The S-WdgM monitors the program flow and timing constrains of so-called Supervised Entities. When it detects a violation of the preconfigured program flow and timing values, it takes a number of configurable actions to recover from this state.

The Safe Watchdog Manager Stack consists of the following embedded software modules:

- Safe Watchdog Manager software module (hardware independent)
- Safe Watchdog Interface software module (hardware independent)
- Safe Watchdog Driver software module (hardware dependent),

and the Safe Watchdog Manager Stack configuration generators:

- Safe Watchdog Manager configuration generator (hardware independent)
- Safe Watchdog Interface configuration generator (hardware independent)
- Safe Watchdog Driver configuration generator (hardware dependent)

and the Safe Watchdog Manager Stack configuration verifier

Safe Watchdog Manager configuration verifier (hardware independent)

This document represents the release notes for the Safe Watchdog Manager module only.

The **Safe Watchdog Manager** is compatible to the WdgM module as specified in the AUTOSAR 4.0 and AUTOSAR 3.1 specifications but not fully compliant. For deviations and justifications please see the S-WdgM User Manual.

 Date:
 21.11.2014
 File name:
 S-WdgM_ReleaseNotes.doc
 © TTTech-Automotive GmbH

Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 7

Content of the Module Release 2

Title	Version*)	Author	Description
WdgM/	3.4.6		S-WdgM Module
S-WdgM_ReleaseNotes.pdf			
Description/	3.3.3	TTTech	
WdgM_Bswmd_A4.arxml			For AUTOSAR 4.0.x environment
WdgM_Bswmd.arxml			For AUTOSAR 3.1.y environment
Doc_SafetyManual/	2.3.28		
S-WdgM_SafetyManual.pdf			
Doc_SafetyCase/	1.1.0		
S-WdgM_SafetyCase.pdf			
Doc_TechRef/	3.3.1	TTTech	
S-WdgM_UserManual.pdf			User Manual
Generator/	3.3.15	TTTech	
LICENSE			
Wdg_Mgr_Cfg_Gen.exe			
GenTool_Ead/	2.0.12	TTTech	
SWC_WdgM_A4.xsl			For AUTOSAR 4.0.x environment
SWC_WdgM.xsl			For AUTOSAR 3.1.y environment
Identifier.xml			
Generation.xml			
Generation_A4.xml			
Implementation/	3.3.3	TTTech	
WdgM.c			Watchdog Manager - Main
WdgM_Checkpoint.c			Watchdog Manager - Checkpoint
WdgM_Cfg.h			Watchdog Manager -
			Configuration structures
WdgM.h			Watchdog Manager - API
			declaration
Verifier/	1.2.11	TTTech	
wdgm_verifier.dll			S-WdgM Configuration Verifier
libwdgm_verifierdll.a			S-WdgM Configuration Verifier lib
wdgm_verifier.h			S-WdgM Configuration Verifier
wdgm_verifier_types.h			S-WdgM Configuration Verifier
wdgm_verifier_version.h			S-WdgM Configuration Verifier
verify_wdgm_header.xsl			S-WdgM Configuration Verifier
verify_wdgm_source.xsl			S-WdgM Configuration Verifier
VerifierTools/	1.0.0		

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH

Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 8

MinGW/	5.1.6	MinGW	
w32api-3.13-mingw32-dev.tar.gz			
mingwrt-3.15.2-mingw32-dll.tar.gz			
mingwrt-3.15.2-mingw32-dev.tar.gz			
MinGW-5.1.6.exe			
mingw.ini			
gcc-core-3.4.5-20060117-3.tar.gz	3.4.5		
binutils-2.19.1-mingw32-bin.tar.gz			
xsltproc/	1.0.0	xsltproc	
zlib1.dll			
xsltproc.exe			·

libxslt.dll

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH

 Document Title:
 Release Notes
 Doc.No:
 D-SAFEX-RP-70-012
 Page 9

3 Change history

This chapter describes the changes in each released version.

3.1 Changes with version 3.4.6

Issue Nr.	Area	Found Wk	Issue title	Release status
69689	G	wk47	`WdgM_PBcfg.h` shall #include `WdgM_Cfg.h`	S

The issue description (issue69689):

The file `WdgM_PBcfg.h` uses a type `WdgM_ConfigType` but does not #include the header file where that type is defined. This situation causes normally no problems because the corresponding C source file `WdgM_PBcfg.h` has the following #include directive:

#include "WdgM.h"

#include "WdgM_PBcfg.h"

Where "WdgM.h" includes the necessary `WdgM_Cfg.h`.

The current release improved this point and the `WdgM_PBcfg.h` includes the `WdgM_Cfg.h` directly.

3.2 Changes with version 3.4.5

S-WdgM module was not changed in this release, the Safety Case document was added only.

Issue Nr.	Area	Found	Issue title	Release
		Wk		status
68941	G	44	Safe Execution - Remove Cross Cutting Checks in	S
		/2014	the WdgM Config Generator	
68932	G	44/	Wdg Config Generator RH850P1x_TLE4473	S
		2014	missing paramterers	

The change description (issue68941):

The cross-cutting checks are removed from S-WdgM Generator. The Watchdog Manager Config Generator should not attempt to verify the Watchdog Driver's data because this is on this level not necessary. The removed cross-check parameters are the following:

- WdgGeneral/WdgInitialTimeout
- WdgSettingsConfig/WdgWindowStart
- WdgSettingsConfig/WdgSlowModeMax
- WdgSettingsConfig/WdgFastModeMax

 Date:
 21.11.2014
 File name:
 S-WdgM_ReleaseNotes.doc
 © TTTech-Automotive GmbH

Document Title: Release Notes Doc.No: D-SAFEX-RP-70-012 Page 10

Release status:

Closed as obsolete

Area:

3.3 Changes with version 3.4.4

S-WdgM module was not changed in this release, the Safety Case document was added only.

Issue Nr.	Area	Found Wk	Issue title	Release status
65369	D		Release Management Tasks for 1.26.1 CW 31/2014	S

3.4 Changes with version 3.4.3

S-WdgM module changes and corrections

Issue Nr.	Area	Found	Issue title	Release
		Wk		status
62326	all		Safe Execution Release 1.26.0 - Release	S
			Management Tasks	
			(include collection of issues for this release)	

3.5 Changes with version 3.4.2

S-WdgM module changes and corrections

Issue Nr.	Area	Found	Issue title	Release
		Wk		status
61768	G	Wk15	SafeExecution - Deactivate cross-cutting tests to avoid problems with AS3-compatible Third-Party Drivers	S

 Date:
 21.11.2014
 File name:
 S-WdgM_ReleaseNotes.doc
 © TTTech-Automotive GmbH

Document Title: Release Notes Doc.No: D-SAFEX-RP-70-012 Page 11

3.6 Changes with version 3.4.1

S-WdgM module changes and corrections

Issue Nr.	Area	Found Wk	Issue title	Release status
61023	G+E		Issue collection for Autosar4.x S-WdgM issues and	S
			Autosar compatibility of the S-Wdglf module.	

3.7 Changes with version 3.4.0

S-WdgM module changes and corrections

Issue Nr.	Area	Found Wk	Issue title	Release status
59931	G+E		API and generator points for AUTOSAR 4, reported by Vector	S

3.8 Changes with version 3.3.2

S-WdgM module changes and corrections

Issue Nr.	Area	Found	Issue title	Release status
58478	G	Wk 48	-	S
58479	G	Wk 48	Add hint re need to provide driver data in EDF	S

3.9 Changes with version 3.2.0

S-WdgM module changes and corrections:

Issue Nr.	Area	Found	Issue title	Release
				status
51893	G	Wk 6	Different checks for third-party drivers	S
51859	G	Wk 6	Use symbolic IDs for SEs and CPs	S
52428	G	Wk 10	#define constants moved from source to header file	S
52577	G	Wk 11	Do not assume system-wide unique CP names	S

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH



Project Name: Safe Watchdog Manager Document Title: Release Notes Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Page 12

Release status:

Area:

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH

 Document Title:
 Release Notes
 Doc.No: D-SAFEX-RP-70-012
 Page 13

3.10 Changes with version 3.1.2

Issue	Area	Found	Issue title	Release
Nr.		in Wk		status
52577	G	Wk6	Do not assume system-wide unique CP	0
			names	
			with the same name in different Supervised	
			Entities then the generator can generate	
			wrong configurations.	

3.11 Changes with version 3.1.1

S-WdgM module changes and corrections:

Issue Nr.	Area	Found in Wk	Issue title	Release status
52281	V	Wk08	Deactivate the test 36. The test is obsolete.	S

Release status:

Area:

3.12 Changes with version 3.1.0

S-WdgM module changes and corrections:

Issue	Area	Found	Issue title	Release
Nr.		in Wk		status
50917	V		he WDGM_STATE_CHANGE_NOTIFICATION Correctly.	8
50131	G	Wk45	WdgM and WdgIf config generators must work together with unsupported Wdg Drivers	S
49656	V		Verifier - Sorting of parameters might make test results wrong.	S

 Date:
 21.11.2014
 File name:
 S-WdgM_ReleaseNotes.doc
 © TTTech-Automotive GmbH

Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 14

48637	G	Wk36	CP ID is used as CFG array ID,	S
			generator stops generating)	
51164	D	Wk02	Safety Manual update	S
51222	D	Wk02	Safety Case update (version numbers)	S

Release status:

Area:

3.13 Changes with version 3.0.3

S-WdgM module changes and corrections:

Issue	Area	Found	Issue title	Release
Nr.		in Wk		status
50131	G	Wk45	WdgM and WdgIF config generators must	S partly
			work together with unsupported Wdg Drivers	
49950	Е	Wk45	WdgM: line 792: warning (dcc:1516):	S
			parameter CallerID is never used	
49735	Е	Wk44	WdgM: The	S
			WdgM_GlobalSuspendInterrupts() should be	
			defined "extern" and renamed to	
			GlobalSuspendInterrupts()	
49837	Е	Wk44	Common Suspend/Restore Interrupt routines	S
			shall be used	
48420	Е	Wk44	Deactivating an active SE should rise in some	S
			cases DET report	
48667	G	Wk43	Generator shall generate constants with 'u'	S
			sufix	
48637	G	Wk 36	The CP and SE IDs must be strict ordered.	0
		Change	Otherwise the Generator rises an error.	
		request		
48601	SWC		Uneven implementation of port defined	S
			argument values for port interface	
			<wdgm_globalmode></wdgm_globalmode>	
48993	E		Wdglf_GetTickCounter() writes to WdgM	S
			global memory	
48818	G		S-WdgM Code segment fixed in the	S
			WdgM_MemMap.h file	

Release status:

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH

Safe Watchdog Manager Project Name: Version: 3.4.6

Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 15

Area:

3.14 Changes with version 2.0.7

Test release for new versioning and delivery structure. This is not a customer version. Used internally only.

S-WdgM module changes and corrections:

Embedded Code changes:

none

Generator changes:

none

Verifier changes:

none

Documentation changes:

none

DaVinci interface changes:

None

3.15 Changes with TTTech Release 1.9.3: S-WdgM Subpackage 2.0.6

This release contains an update of the Watchdog Manager Configuration Verifier. The release is compatible with the embedded code basis of the release 1.9.0 and documentation release 1.9.1 and 1.9.2

Embedded Code changes:

none

Generator changes:

none

Verifier changes:

[46858] Verify all relevant WdgM global settings

[48716] Detect NULL pointers

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH Author: TTTech

Version: 3.4.6

Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 16

Documentation changes:

- S-WdgM User Manual update
- S-WdgM Stack Safety Case new

DaVinci interface changes:

None

Open issues in this release:

Issue	Area	Issue title	Release	
Nr.			1.9.3	

48993

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH

Document Title:Release NotesDoc.No:D-SAFEX-RP-70-012Page 17

3.17 Changes with Release 1.9.1: S-WdgM Subpackage 2.0.4

This release contains S-WdgM documentation and S-WdgM Verifier only. The documentation in this release is compatible with the embedded code basis of the release 1.9.0 (Subpackage 2.0.3)

Embedded Code changes:

none

Generator changes:

none

Verifier issues:

• , limitations,

Documentation changes:

- [48745] S-WdgM Safety Manual Formal Review
- [48722] S-WdgM User Manual Review

3.18 Changes with Release 1.9.0: S-WdgM Subpackage 2.0.3

Open issues in this release:

Issue	Area	Issue title	Release
Nr.			1.9.0
48624	Е	MPC56xx Driver MISRA issues.	S
48607	Е	Wdglf Interface MISRA issues.	S
48583	Е	WdgM Manager MISRA issues.	S
47956	SWC	Removed unused runnable entities.	S
47459	Е	WdgM_MainFunction should have a reentrancy check.	0
47828	Е	Service IDs of an API function differ from AUTOSAR	S
47832	Е		0
		error response.	
48320	E, G	The first Supervision cycle should have definable Alive	S
		test.	
48320]	Е	The ProgramFlowViolationCnt is wrongly incremented	S
48298	E, G	The OS Partition Reset makes compile warning problem	S
46101	Т	WdgM: Unit test for the Autosar 3.1 compatibility	S
46382	V	Defines are not checked for correct value (STD_ON,	S
		STD_OFF)	
46977	SWC	WdgM: Each Entity may have zero or more End	S
		Checkpoints	
47905	SWC	Location of xxx_SEC_CONST_UNSPECIFIED +	S
		xxx_SEC_CODE	

 Date:
 21.11.2014
 File name:
 S-WdgM_ReleaseNotes.doc
 © TTTech-Automotive GmbH



Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 18

47386	SWC	Special Handling for Callback in Service Component Description	0
47000	SWC	·	S
47990	SVVC	The WdgM_SetMode() need to be added to the 3.1	3
47956	SWC	compatibility mode	S
47956	SVVC	WdgM Generator creates runnable trigger which is not	3
42841	SWC	configured	S
		Service Component always has all version's APIs	S
47328	E E	S-WdgM: initialize uninitialized local variable,	
47131	E	Cover combined X-Y-Monitoring violations in status FAILED	S
44842	E	WdgM: Magic constants should not be used when not	0
		necessary (Disable automatically generated typedefs)	
45280	G	Wdgx: The RAM sections of WdgM, Wdg should be	S
		related to an Application only	
45566	Е	WdgM: Configuration checks only if	0
		WdgMDevErrorDetect is off	
45709	E	Safe WdgM - Alive Counter overrun	S
45814	Е	WdgM: Update Copyright information in embedded codes	S
45827	Е	WdgM: Add AUTOSAR _AR_ Version macros	S
46044	E	S-WdgM: protect sensitive data accesses from interrupts	S
46383	E	ascSC is assumed to be defined but this is not checked	S
46388	Е	INVALID_OSAPPLICATION is not necessarily 0xFF in	S
		Os.h	
46464	E	WdgM: remove not used code when API_3_1 selected	0
46816	Е	Safe WdgM - error from WdgIf during initialization	С
46819	G	S-WdgM: 0xFFFF tolerance values prevent from going to EXPIRED	S
46820	E	WdgM: AUTOSAR Compiler abstraction	S
46993	E	WdgM: Fixing the external function names	S
46574	G	avoid division by zero if Ticks/second = 0	S
46794	G	reject multiple DM elements for one transition	S
40734			
46920	G	checkpoint attribute "startsAGlobalTransition" is now	S
		correctly computed	
44628	G	remove compiler warning ({{0}, {1},} instead of {0, 1}	S
47177	G	reject configurations not having a 1:1:1 relationship for	S
		driver/interface/watchdog	
47058	G	disable OS Partition Reset in generator	S

Release:

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH





Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 19

Area:

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH

 Document Title:
 Release Notes
 Doc.No: D-SAFEX-RP-70-012
 Page 20

3.19 Changes with Release 1.8.2: S-WdgM Subpackage 1.8.2

Embedded Code BugFixies:

- [47131] Cover combined X-Y-Monitoring violations in status FAILED
- [45709] Safe WdgM Alive Counter overrun
- [45827] WdgM: Add AUTOSAR AR Version macros
- [46044] S-WdgM: protect sensitive data accesses from interrupts
- [45280] Wdgx: The RAM sections of WdgM, Wdg should be related to an Application only
- [47328] S-WdgM: initialize uninitialized local variables

Configuration Generator BugFixies:

- [46574]: avoid division by zero if Ticks/second = 0
- [46794]: reject multiple DM elements for one transition
- [46920]: checkpoint attribute "startsAGlobalTransition" is now correctly computed
- [44628]: remove compiler warning ({{0}, {1}, ..} instead of {0, 1}
- [47177]: reject configurations not having a 1:1:1 relationship for driver/interface/watchdog
- [47058]: disable OS Partition Reset in generator

3.20 Changes with Release 1.8.0: S-WdgM Subpackage 1.8.0

- The Safety Manual revorked, the not safety related informations are moved to the User Manual.
- [45700] Trigger Mode implemented (Simplified SetMode() function)
- [45927] RememberedEntityId replaced by global transition flags
- [45959] Periodicity of deadline and program flow tolerances repaired
- [46206] Minor changes to increase test coverage

3.21 Changes with Release 1.7.0: S-WdgM Subpackage 1.7.0

- [45210] Hardware TickCounter implemented
- [45572] WdgM_GetLocalStatus() adapted, WdgMEnableEntityDeactivation flag was moved
- [45663] tick count diff calculation repaired
- [45388] Mcu_PerformReset() removed from WdgM_MainFunciton.

3.22 Changes with Release 1.6.0: S-WdgM Subpackage 1.6.0

- [44418] Checksum for configuration added
- [44978] SE deactivation/activation variable protection in the GS memory added
- [45008] Partition reset partly corrected, the Entity reset was added.

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH

 Document Title:
 Release Notes
 Doc.No:
 D-SAFEX-RP-70-012
 Page 21

[45066] Refactoring, MISRA check corrections

3.23 Changes with Release 1.5.0: S-WdgM Subpackage 1.5.0

- [43770] The write access of the MainFunction() to the entity memory removed.
- [44107] Deadline, Program flow monitoring debouncing parameters optimization
- [43913] MainFunction() interrupted by Checkpoint() corrections
- [44257] Check for Number of S-WdgM Ticks in SupervisionCycle added
- [43912] The direct reset (hardware reg. access) was removed from CheckpointReached()

3.24 Changes with Release 1.4.0: S-WdgM Subpackage 1.4.0

- The documentation structure was changed. Each module (Manager, Interface and Driver) has now
 an own User Manual, Safety Manual and Release Notes. The changes mentioned in this chapter
 represents the S-WdgM changes only.
- [42537] WDGM_DEM_SUPERVISION_REPORT define moved to WdgM_Cfg_Feature.h file
- [42797] Compiler warnings removed, the SE deactivation/activation simplified
- [42943] SE Deactivation/Activation issue removed
- [43092] global transitions repaired internal global transition flag introduced
- [43881] Unused variable removed

3.25 Changes with Release 1.3.1: WdgM Subpackage 1.3.1

The Wdg_MPC56xx_bswmd.arxml file was changed only. The xml element Wdg_Impl was removed from the file by Mr. Kalmbach at Vector. The element causes a problem in GENy.

3.26 Changes with Release 1.3.0

Embedded code:

- [42477] Notification in GLOBAL_STATE_STOPPED was not necessary and was removed
- [42503] Error message to DEM in GLOBAL_STATE_STOPPED is now reported correctly
- [42509] Check for a valid global transition repaired in the case of a local initial checkpoint.
- [42249] Added the new MPC56xx family platform, new S-Wdg driver created

Generators:

Added new MPC56xx family platform

3.27 Changes with Release 1.2.0: WdgM Subpackage 1.2.0

Embedded code:

 Date:
 21.11.2014
 File name:
 S-WdgM_ReleaseNotes.doc
 © TTTech-Automotive GmbH



 Document Title:
 Release Notes
 Doc.No:
 D-SAFEX-RP-70-012
 Page 22

• For the global Disable/Enable interrupts the AUTOSAR Schedule Manager interface is now used instead of the operating system interface. (Now the SchM_WdgM.h needs to be included)

- When the RTE is used, then the S-WdgM uses the defines and typedefs generated by RTE instead
 of the S-WdgM internal typedefs and defines (switchable with WDGM_USE_RTE)
- Primary Reset path instead of Secondary reset path is used when the WDGM_IMMEDIATE_RESET==STD_ON is selected. This change was done to guarantee safe reset. (The previously used external Mcu_PerformReset() function is a QM function)
- The Timebase Tick counter check (stuck-in and negative count) was corrected in the WdgM MainFunction()
- Similar to the S-WdgM the S-Wdg has now a Wdg_MemMap.h file. So it is possible to place the Wdg variables to a memory section predefined by DaVinci Configurator.

Generators:

- better error handling
- XSLT Stylesheet now includes `WdgM_MainFunction` and `WdgM_UpdateTickCount` as runnables.
- Drivers/platforms now can be identified correctly regardless of the SHORT-NAMEs chosen by users

ECU description file change:

Release 1.2.0 uses SUB-PACKAGEs for organizing platform-related data inside ECU description file. ECU description files created for previous versions have to be adapted slightly - otherwise the code generators may not be able to find the platform data. Please follow these steps:

- 1. Open the ECU Description file with a text editor
- 2. Find <DEFINITION-REF> elements in the ECU description file containing `/TTTECH/Wdg` or `/TTTECH/WdgImpl`
- 3. Replace the `TTTECH/Wdg` substring with `TTTech/TMS570LS3x/Wdg` and /TTTECH/WdgImpl` with /TTTECH/TMS570LS3x/WdgImpl`
- 4. Save your changes

3.28 Changes with Release 1.1.0: WdgM Subpackage 1.1.0

Embedded code:

- The AUTOSAR 3.1 functionality Deactivate / Activate entity was implemented.
- The Callback Notification was implemented.
- The entities initialization in the WdgM_Init() was corrected.

•

- The MPC5604B Safe Watchdog driver was implemented
 - N
 - one of the supervisor modes. This means that the WdgM_MainFunction(), which periodically triggers the watchdog, must run in a supervisor mode!
 - This first version of the MPC5604B Safe Watchdog driver was developed and tested using the Freescale CodeWarrior Compiler 5.9.0.
 - Following configuration sets were verified: fSIRCkhz=128, interruptThenReset=false, hardLock=false, stopModeControl=true, debugModeControl=true, WdgDevErrorDetect=true, WdgDemReport=true, WdgDisableAllowed=true, WdgVersionInfoApi=true.

 Date:
 21.11.2014
 File name:
 S-WdgM_ReleaseNotes.doc
 © TTTech-Automotive GmbH

Document Title:Release NotesDoc.No:D-SAFEX-RP-70-012Page 23

Generators:

Wdg_Mgr_Cfg_Gen.exe generates code to support supervised entity activation/deactivation and callback notifications.

Wdg_lf_Cfg_Gen.exe generates code for the MPC5604B driver and corresponding interface.

3.29 Changes with Release 1.0.0: WdgM Subpackage 1.0.0

- The Safe Watchdog Interface embedded code was split in to two modules:
 - 1. Safe Watchdog Interface, is now hardware independent
 - 2. Safe Watchdog Driver, is hardware dependent
- The Mode switch through the WdgM_Init was removed.
- There is now possibility to disable interrupts while the Global shared data are manipulated
- Some enum definitions in the S-WdgM API (like LOCAL_STATUS_OK) was changed to AUTOSAR specified #defines
- Changes in the generators:
 - The generators generates now additionally WdgM_Cfg_Features.h, Wdglf_Cfg_Features.h, Wdg_TMS570LS3x_Cfg_Features.h files.
 - The generators generates now additionally WdgM_MemMap.f file.
- Changes in the bswmd and swc files:
 - Feature definitions are added
 - Software version and vendor info was added
 - · Obsolete 3.1 items was deleted
 - DEFINITION-REF elements now contains paths beginning with TTTECH instead of AUTOSAR
 - The bswmd files are now schema compliant.
 - At typedefs WdgM_CheckpointIdType, WdgM_SupervisedEntityIdType was the maximum value changed to 65535.

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH



Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 24

4 **Test status**

The S-WdgM integration tests based on the issue 69689 were performed. No findings.

All test results are positive.

Date: 21.11.2014 File name: S-WdgM_ReleaseNotes.doc © TTTech-Automotive GmbH Author: TTTech

Version: 3.4.6

 Document Title:
 Release Notes
 Doc.No:
 D-SAFEX-RP-70-012
 Page 25

5 Known issues, limitations, updates

Known issues:

For known issues please see the chapter Change history above.

Functional limitations of current version:

Not known.

Updates:

Current release represents a S-WdgM module for AUTOSAR 4.0.x and AUTOSAR 3.1.y.

Note, that the S-WdgM Configuration generator reads the AUTOSAR version from ECU description file and generates a define <code>WDGM_AUTOSAR_4_x STD_ON"</code> in case of Autosar 4.x. Dependent on this define the embedded code uses the appropriate Autosar 4.0.x functionality.

 Date:
 21.11.2014
 File name:
 S-WdgM_ReleaseNotes.doc
 © TTTech-Automotive GmbH

Version: 3.4.6 Doc.No: D-SAFEX-RP-70-012 Document Title: Release Notes Page 26

Abbreviation and glossary

Acronym / Term	Meaning
СР	Checkpoint
EDF	ECU Description File (.arxml file used as input to the configuration generator)
SE	Supervised Entity
os	Operating System
SCx	Scalability Class (of an Operating System)
S-WdgM	Safe Watchdog Manager (TTTech product, platform independent part)
S-Wdglf	Safe Watchdog Interface (TTTech product, is the platform independent part)
S-Wdg	Safe Watchdog Driver (TTTech product, is the platform dependent part)
WdgM	Watchdog Manager (module according AUTOSAR specification)
[xxxxx]	TTTech internal issue tracking number.

Date: 21.11.2014 © TTTech-Automotive GmbH File name: S-WdgM_ReleaseNotes.doc Author: TTTech

Version: 3.4.6