

Dataset 3: Attitude Control System

System: Reaction Wheel Assembly B

Status: CAUTION

Voltage: 12.1V

Temperature: 68.9°C

Pressure: 1011 hPa (Internal housing)

Cycle Count: 89,442

Anomaly Report: Minor vibration detected at 450 RPM. Bearing friction slightly above nominal parameters; increased thermal monitoring initiated for the next 6-hour interval.