

CORDLESS DRILL

CRATE
C-045

REQUIRED PPE



EYE PROT.



SCAN FOR MANUAL

RETURN CHECKLIST

- ☐ battery on charger
- ☐ bits returned to case
- ☐ chuck key present
- ☐ crate swept clean
- ☐ any damage reported