

(a) Peak overpressure
Peak overpressure 2D / 1D
Radius [m]
G2, 0°
G2, 45°
G2, 90°
G2b, 0°
G2b, 45°
G2b, 90°
(b) Positive impulse
Positive impulse 2D / 1D
Radius [m]
(c) Unburnt Al and CO
Mass / initial Al mass
Time [ms]
Al, 1D
CO, 1D
Al, G2
CO, G2
Al, G2b
CO, G2b
(d) G2b, 0.5 ms
(e) G2b, 1 ms
(f) G2b, 1.3 ms
y (axis) [m]
x [m]
Products fraction (C/(C+N) / 0.449)