
Calibration set U1



Which N good parts set t_α; the size N

Type A: 1000 resampled calibration sets vs Beta(N − k + 1, k); curves: N = 50, 100, 500

Normal reference U3



Which M good parts form the bank B; the size M

Type A: 5 bank draws × 5 support draws; M = 5, 10, 20, 50

Support set U3




Which K examples represent each defect type; K

Type A: 5 support draws (crossed with the bank)

Reported results: false-reject rate, escapes per 1000 parts, balanced accuracy, latency and energy


Test sample U3



Finite number of test parts and objects

Type A: bootstrap over parts and objects; dots: measured gain per VisA object


Influence quantities U4



Lighting, blur, noise, shift, rotation, JPEG

Sensitivity with and without recalibration; agreement over repeats

Computing platform U6



Precision, engine, process session, clock and temperature

Type A: 10 sessions, 5 energy windows; Type B: numerical tolerance