Frujikura DDK(THAILAND) Ltd.		MRR/MIR Report			Issue No: QA-18-02-010 Date: 2018/2/27			
								DDK (THAILAND) LTD.
Navanakorn Industrial Estate 55/25 Klong-Luang, Pathumthani 12120 T		Material Impr		Issue By: Winida W.				
Thong Edding; Fathamaidin 12120-11	ranara			Nonconformity I	Degree:			
	☐ Critical	Maj		Minor				
Item Number:	Reject Found Process / Line							
2141658 BB35C-PAA24AA3-522E-DLF				Warehouse	QA In	coming	In-process	
					ot Number:			
18DD048				180210-5-Q-0002 /0003/0004/0005				
Lot Q'ty/QA Sampling Q'ty:		Defect Q'ty:	%Defect: 0.67%					
Detail&Picture:	00 pcs			Problem Category				
					Quality	Appear		
						Dimension		
Our assembly found I/M short mold (through) problem from BB35C-PAA24AA3-522E-DLF.						Function Others		
This defect occur <u>random cavity</u> and <u>outside reel</u> which we found defect from block insert 4 reel. By the way we hold connector qty. 96 Kpcs and block insert qty. 100.29 Kpcs					Pls. specify:			
by the may we had connector qty, so kpes and block insert qty. 100,23 kpes					, ioi speeny :			
Picture defect.					Delivery Missing Part(s)			
					☐ No Inspection Record ☐ Wrong Delivery			
Transaction of the second of t					☐ No Delivery Tag			
						☐ Wrong L		
					Incomplete Documents			
					Others			
					Pls. specify	·		
Diamanitian an Balanta I Bart								
Disposition on Rejected Part	s:	8	20 10 20 20 20					
Disposition		Detail/Estimate Cost			Remark			
Special Accept	Reason						9	
Special Accept	-							
Rescreen	Q'ty (pcs) 96,000	Rescreen time(hrs)	Rate Charge(Baht)	Cost(Baht) 0.00				
Rework	Q'ty (pcs)	Rework time(sec)	Rate Charge(Baht)	Cost(Baht)			b u	
Return	Q'ty (pcs)	Cost per piece(baht)		0.00 Cost(baht)				
	100,290.00 Q'ty (pcs)	Cost per piece(Baht)	0.00 Cost(Baht)					
Scrap Connector			0.00			1		
Scrap Part	Q'ty (pcs)	Cost per piece(Baht)	Cost(Baht) 0.00					
Replacement	Invoice No.: Ship Date:							
			Total Cost(Baht)					
#6.								
	F							
Request Supplier:					0 10		×	
1) Rescreen parts :	Request Identify_							
2) Part new improve	ement : Request Ide	entify						
Demont to DDK T.D in	1-101-1		0.84 1.140				,	
Report to DDK-T Required:	Initial response	e due date ion report due date	2 March'18 6 March '18	(Response within (Response within		•		
Suplier Response:		ion report due date	o maron 10	_(response within	o working da	ys)	1 1	
Disposition of Inventory	II							
Location	Q'ty	Lot No.		Dispsotion		Identify	- 10	
WIP/Product								
Warehouse In-transit								
and appearance of the same of							N 22	
Risk Lot Please refer to the attached sheet.								
3. Containment Action								
					Supplier Signatories			
					Preparead	Preparead A. kobayashi		
Banks Bata	225			20	Checked	TTA	1-10	
Reply Date	, SOP Reque	est, Please Attach				1- (a/fe	na na	
					Approved D. Kobayashi			
							FQA-459/ 161115 (Page 1/2)	