


EtherNet Port







HDMI Port







USB 3.1 Port







GPIO Port






Test points







LED Indicators





USB 2.0 Debug







2 Terminal Screw terminal for power






User Buttons





CSI Connector



Buck convertors

