



U.S. Department
of Transportation

**Pipeline and
Hazardous
Materials Safety
Administration**

400 Seventh Street, S.W.
Washington, D.C. 20590

MAY 9 2005

Mr. Patrick Ginn
Piper Metal Forming Corp.
795 Sam T. Barkley Drive
New Albany, MS 38652


Dear Mr. Ginn:

Your application, 14156-N, dated February 18, 2005, is returned herewith because it failed to meet the requirements of 49 CFR 107.105 by not providing the fundamental design qualifications that include the following:

- Heat treatment procedure
- Fracture performance testing
- Fatigue performance testing
- Operational and environmental testing
- Burst testing
- Mechanical test results (e.g., elongation, fracture toughness, etc.)

Please resubmit your application when it is complete.

Sincerely,


Delmer F. Billings

Director

Office of Hazardous Materials
Exemptions and Approvals

Enclosure