



Dave noticed that the pressure on the 2 tyres have fallen to critically low levels over the past 3 hours of operation

Tyre placement












DT5260

active since 11/03/2016


Service History



Rear Left Tyre Serial: 055ASAB121112

Current Pressure: 160 PSI

Generate Work Order



Detection point

