


REVISION INFO

V1.0.0 – INITIAL DESIGN

AREAS OF IMPROVEMENT
- CONSOLIDATE 0603/0805
- PROG HEADER PLACEMENT IS TERRIBLE, HANGS OVER BOARD EDGE, INTERFERES WITH CAP
- BATT HOLDER SNAPS OFF EASILY IF DROPPED. PTH WOULD BE BETTER.

TACTICAL SNACKS

Sheet: /
File: hum_hw.kicad_sch

Title: HUM_HW

Size: A4	Date: 2026-10-14	**Rev: 1.0.0**
KiCad E.D.A. 10.0.6		Id: 1/1