





Name	Value	Data Type	Scope
DWELL		TIMER	MainProgram
Process Timer			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
DWELL - MainProgram/MainRoutine - *4(TON)			
DWELL.PRE	15000	DINT	
Process Timer Preset			
DWELL.PRE - MainProgram/HMI_ROUTINE - 3(DIV)			
DWELL.PRE - MainProgram/MainRoutine - *1(MOVE), *2(MOVE), *3(MOVE)			
DWELL.ACC	0	DINT	
Process Timer Accumulated			
DWELL.ACC - MainProgram/HMI_ROUTINE - 4(DIV)			
DWELL.EN	0	BOOL	
Process Timer Enabled			
DWELL.EN - MainProgram/MainRoutine - 4(XIC), 5(XIC)			
DWELL.TT	0	BOOL	
Process Timer			
DWELL.DN	0	BOOL	
Process Timer Complete			
DWELL.DN - MainProgram/MainRoutine - 4(XIO)			
HMI_ACC	0.0	REAL	MainProgram
Operator Panel Timer Accumulated			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
HMI_ACC - MainProgram/HMI_ROUTINE - *4(DIV)			
HMI_PB	2	INT	MainProgram
Operator Panel Pushbuttons			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
HMI_PB - MainProgram/HMI_ROUTINE - 0(EQ), 1(EQ), 2(EQ)			
HMI_PB_1	0	BOOL	MainProgram
Operator Panel Pushbutton 1			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
HMI_PB_1 - MainProgram/HMI_ROUTINE - *0(OTE)			
HMI_PB_1 - MainProgram/MainRoutine - 1(XIC)			
HMI_PB_2	0	BOOL	MainProgram
Operator Panel Pushbutton 2			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
HMI_PB_2 - MainProgram/HMI_ROUTINE - *1(OTE)			
HMI_PB_2 - MainProgram/MainRoutine - 2(XIC)			
HMI_PB_3	0	BOOL	MainProgram
Operator Panel Pushbutton 3			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
HMI_PB_3 - MainProgram/HMI_ROUTINE - *2(OTE)			
HMI_PB_3 - MainProgram/MainRoutine - 3(XIC)			
HMI_PRE	0.0	REAL	MainProgram
Operator Panel Timer Preset			
Constant	No		

HMI_PRE (Continued)

External Access:	Read/Write
OPC UA Access:	None
<i>HMI_PRE - MainProgram/HMI_ROUTINE - *3(DIV)</i>	




Name	Value	Data Type	Scope
DWELL		TIMER	MainProgram
Process Timer			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>DWELL - MainProgram/MainRoutine - *4(TON)</i>			
DWELL.PRE	15000	DINT	
Process Timer Preset			
<i>DWELL.PRE - MainProgram/HMI_ROUTINE - 3(DIV)</i>			
<i>DWELL.PRE - MainProgram/MainRoutine - *1(MOVE), *2(MOVE), *3(MOVE)</i>			
DWELL.ACC	0	DINT	
Process Timer Accumulated			
<i>DWELL.ACC - MainProgram/HMI_ROUTINE - 4(DIV)</i>			
DWELL.EN	0	BOOL	
Process Timer Enabled			
<i>DWELL.EN - MainProgram/MainRoutine - 4(XIC), 5(XIC)</i>			
DWELL.TT	0	BOOL	
Process Timer			
DWELL.DN	0	BOOL	
Process Timer Complete			
<i>DWELL.DN - MainProgram/MainRoutine - 4(XIO)</i>			
HMI_ENABLE_DISABLE	0	BOOL	MainProgram
Allows Hardwired Panel			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>HMI_ENABLE_DISABLE - MainProgram/MainRoutine - 1(XIC), 1(XIO), 2(XIC), 2(XIO), 3(XIC), 3(XIO)</i>			
HMI_PB_1	0	BOOL	MainProgram
Operator Panel Pushbutton 1			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>HMI_PB_1 - MainProgram/HMI_ROUTINE - *0(OTE)</i>			
<i>HMI_PB_1 - MainProgram/MainRoutine - 1(XIC)</i>			
HMI_PB_2	0	BOOL	MainProgram
Operator Panel Pushbutton 2			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>HMI_PB_2 - MainProgram/HMI_ROUTINE - *1(OTE)</i>			
<i>HMI_PB_2 - MainProgram/MainRoutine - 2(XIC)</i>			
HMI_PB_3	0	BOOL	MainProgram
Operator Panel Pushbutton 3			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>HMI_PB_3 - MainProgram/HMI_ROUTINE - *2(OTE)</i>			
<i>HMI_PB_3 - MainProgram/MainRoutine - 3(XIC)</i>			
ONE_SHOT		SINT[1]	MainProgram
One Shot Control Array			
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
ONE_SHOT[0]	0	SINT	
One Shot Control Array			
ONE_SHOT[0].0	0	BOOL	
One Shot Control Array			
<i>ONE_SHOT[0].0 - MainProgram/MainRoutine - *1(ONS)</i>			

ONE_SHOT (Continued)				
ONE_SHOT[0].1	0	BOOL		
One Shot Control Array				
ONE_SHOT[0].1 - MainProgram/MainRoutine - *2(ONS)				
ONE_SHOT[0].2	0	BOOL		
One Shot Control Array				
ONE_SHOT[0].2 - MainProgram/MainRoutine - *3(ONS)				
 OUTPUT	0	BOOL		MOVE
Process Output				
AliasFor:	Local:4:O.Data.0			
Base Tag:	Local:4:O.Data.0			
Constant	No			
External Access:	Read/Write			
OPC UA Access:	None			
OUTPUT - MainProgram/MainRoutine - *5(OTE)				
PRE_SET_1	10000	INT		MainProgram
Preset No. 1				
Constant	No			
External Access:	Read/Write			
OPC UA Access:	None			
PRE_SET_1 - MainProgram/MainRoutine - 1(MOVE)				
PRE_SET_2	15000	INT		MainProgram
Preset No. 2				
Constant	No			
External Access:	Read/Write			
OPC UA Access:	None			
PRE_SET_2 - MainProgram/MainRoutine - 2(MOVE)				
PRE_SET_3	20000	INT		MainProgram
Preset No. 3				
Constant	No			
External Access:	Read/Write			
OPC UA Access:	None			
PRE_SET_3 - MainProgram/MainRoutine - 3(MOVE)				
 SEL_SW_1	0	BOOL		MOVE
Selector Switch, Position 1				
AliasFor:	Local:3:I.Data.0			
Base Tag:	Local:3:I.Data.0			
Constant	No			
External Access:	Read/Write			
OPC UA Access:	None			
SEL_SW_1 - MainProgram/MainRoutine - 1(XIC)				
Local:3:I.Data.0 - Model/Emulate - *0(Emulate)				
 SEL_SW_2	0	BOOL		MOVE
Selector Switch, Position 2				
AliasFor:	Local:3:I.Data.1			
Base Tag:	Local:3:I.Data.1			
Constant	No			
External Access:	Read/Write			
OPC UA Access:	None			
SEL_SW_2 - MainProgram/MainRoutine - 2(XIC)				
Local:3:I.Data.1 - Model/Emulate - *0(Emulate)				
 SEL_SW_3	0	BOOL		MOVE
Selector Switch, Position 3				
AliasFor:	Local:3:I.Data.2			
Base Tag:	Local:3:I.Data.2			
Constant	No			
External Access:	Read/Write			

SEL_SW_3 (Continued)

OPC UA Access: None
SEL_SW_3 - MainProgram/MainRoutine - 3(XIC)
Local:3:I.Data.2 - Model/Emulate - *0(Emulate)

 START	0	BOOL	MOVE
START Momentary N.O. Pushbutton			
AliasFor:	Local:3:I.Data.14		
Base Tag:	Local:3:I.Data.14		
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
START - MainProgram/MainRoutine - 4(XIC)			



Emulate		
Emulate	emSW	...
EmSELSW	emSELSW	
		0
SW0	Local:3:I.Data.0	0
SW1	Local:3:I.Data.1	0
SW2	Local:3:I.Data.2	0
		0

Name	Value	Data Type	Scope
emSELSW	0	DINT	Model
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>emSELSW - Model/Emulate - 0(Emulate)</i>			
emSW		Emulate	Model
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
<i>emSW - Model/Emulate - *0(Emulate)</i>			
emSW.EnableIn	1	BOOL	
Enable Input - System Defined Parameter			
emSW.EnableOut	1	BOOL	
Enable Output - System Defined Parameter			
Local:3:I		AB:1756_DI:I:0	MOVE
Constant	No		
External Access:	Read/Write		
OPC UA Access:	None		
Local:3:I.Data.0	0	BOOL	
<i>Local:3:I.Data.0 - Model/Emulate - *0(Emulate)</i>			
<i>SEL_SW_1 - MainProgram/MainRoutine - 1(XIC)</i>			
Local:3:I.Data.1	0	BOOL	
<i>Local:3:I.Data.1 - Model/Emulate - *0(Emulate)</i>			
<i>SEL_SW_2 - MainProgram/MainRoutine - 2(XIC)</i>			
Local:3:I.Data.2	0	BOOL	
<i>Local:3:I.Data.2 - Model/Emulate - *0(Emulate)</i>			
<i>SEL_SW_3 - MainProgram/MainRoutine - 3(XIC)</i>			
Local:3:I.Data.14	0	BOOL	
<i>START - MainProgram/MainRoutine - 4(XIC)</i>			

MOVE

MainTask

MainProgram

HMI_ROUTINE

Ladder Diagram	1
Routine Tag Listing.....	2

MainRoutine

Ladder Diagram	4
Routine Tag Listing.....	5

Model

Emulate

Ladder Diagram	8
Routine Tag Listing.....	9