

Field Observation F■221

Issue: Aluminum tray installed in Room C■17 instead of specified Steel CT■1.

Inspector: M. Diaz

Status: Needs correction.