

ASI■04 – Cable Tray Routing & Material Clarification

1. CT■1 in Room C■17 remains Steel.
2. Riser LT■R remains Aluminum.
3. Routing adjusted due to mechanical clash.
4. Related to RFI■112.