

PCO■19 – Material Upsizing ROM

Reason: Change in tray material may affect support spacing.

ROM Cost: +\$18,500

Related Docs: RFI■112, ASI■04.