



Wing Marker Positions at Key Phases (xz projection)
Triangle = wing hinge (root)

$t=0$
 $\phi=0^\circ, \alpha=45^\circ$



$t=T/4$
 $\phi=70^\circ, \alpha=0^\circ$



$t=T/2$
 $\phi=0^\circ, \alpha=-45^\circ$



$t=3T/4$
 $\phi=-70^\circ, \alpha=0^\circ$

