```c
#include "stm32f10x.h"
#include <stdbool.h>
#include <stdint.h>

void delay_initialize(void);
void delay_us(uint32_t x);
void delay_ms(uint32_t y);
void set_time_out(uint32_t timeout);
bool timed_out(void);
```