

VECTO 4.x



Release Notes

Vecto 4.1.3.3415 OFFICIAL RELEASE

08.05.2024

- **Hotfixes**

- CodeEU-638: Incorrect construction payloads for group 9 non-vocational vehicle

Vecto 4.1.1.3413 OFFICIAL RELEASE

06.05.2024

- **Bugfixes**

- CodeEU-615: Multistep freezes after loading VIF chassis
- CodeEU-616: Multistep tool freezes
- CodeEU-619: restore wrong exempted techs in XSD for backwards compatibility
- CodeEU-617: Results change depending the time format
- CodeEU-635: Revert multiple summary in CIF

Vecto 4.1.0.3392 RELEASE CANDIDATE

15.04.2024

- **Features**

CodeEU-577: Add missing mission profiles to vocational and non-vocational

- **Bugfixes (1/4)**

- CodeEU-331: Gear 1 DrivingActionAccelerate: Fail
- CodeEU-367: Gear 1 DrivingActionAccelerate: Fail
- CodeEU-372: ADT Error on Bus Category Primary Vehicle Simulation on VECTO
- CodeEU-373: ADT Error on Bus Category Primary Vehicle Simulation on VECTO
- CodeEU-374: ADT Error on Bus Category Primary Vehicle Simulation on VECTO
- CodeEU-375: ADT Error on Bus Category Primary Vehicle Simulation on VECTO
- CodeEU-393: Finished Run VEH-PrimaryBus_nonSmart Interurban _P32SD_ReferenceLoad with ERROR: 16
- CodeEU-439: 615 (Interurban _P32DD_ReferenceLoad) - absTime: 7129.6359 [s], distance: 53875.9765 [m], dt: 0.6388 [s], v: 0.5098 [m/s], Gear: 1 | DrivingActionAccelerate: Failed
- CodeEU-446: Finished Run VEH-PrimaryBus_nonSmart Interurban _P32SD_ReferenceLoad with ERROR: 16
- CodeEU-449: Finished Run VEH-PrimaryBus_nonSmart Interurban _P32SD_ReferenceLoad with ERROR: 16
- CodeEU-478: Finished Run VEH-PrimaryBus_nonSmart Urban _P31SD_ReferenceLoad with ERROR: 4 (Urban _P31SD_ReferenceLoad) - absTime: 8606.6241 [s], distance: 39112.5127 [m], dt: 1.1131 [s], v: 0.1833 [m/s], Gear: 1 | DrivingActionAccelerate: Failed to find operating poi

Vecto 4.1.0.3392 RELEASE CANDIDATE

15.04.2024

• Bugfixes (2/4)

- CodeEU-481: Finished Run VEH-PrimaryBus_nonSmart Urban _P31SD_ReferenceLoad with ERROR: 4 (Urban _P31SD_ReferenceLoad) - absTime: 8606.6241 [s], distance: 39112.5127 [m], dt: 1.1131 [s], v: 0.1833 [m/s], Gear: 1 |
- CodeEU-488: Finished Run VEH-PrimaryBus_nonSmart Urban _P31SD_ReferenceLoad with ERROR: 4 (Urban _P31SD_ReferenceLoad) - absTime: 8606.6241 [s], distance: 39112.5127 [m], dt: 1.1131 [s], v: 0.1833 [m/s], Gear: 1 | DrivingActionAccelerate: Failed to find operating poi
- CodeEU-494: Finished Run VEH-PrimaryBus_nonSmart Urban _P31SD_ReferenceLoad with ERROR: 26 (Urban _P31SD_ReferenceLoad) - absTime: 8606.6241 [s], distance: 39112.5127 [m], dt: 1.1131 [s], v: 0.1833 [m/s], Gear: 1 | DrivingActionAccelerate: Failed to fi
- CodeEU-420: Finished Run VEH-PrimaryBus_nonSmart Interurban _P32SD_ReferenceLoad with ERROR: 16
- CodeEU-573: Unhandled powertrain architecture Conventional Vehicle to calculate gradability
- CodeEU-582: unhandled powertrain architecture ConventionalVehicle to calculate gradability, 11:44:36.63,
- CodeEU-595: Inconsistency exempted vehicles "Fuel cell vehicle" vs. "FCV Article 9 exempted"
- CodeEU-501: Help regarding VTP vdri format is not up to date in v4
- CodeEU-594: inadequate validation for auxiliaries in completed vehicle XML
- CodeEU-580: Potential error in XML schema v2.4 (exempted vehicles)
- CodeEU-551: Article-10-2 XLRASF5E00G419905
- CodeEU-547: Max ICE Off timespan for buses
- CodeEU-583: Incorrect internal resistance for SuperCap used in factor method

Vecto 4.1.0.3392 RELEASE CANDIDATE

15.04.2024

• Bugfixes (3/4)

- CodeEU-571: Article10-2-issue | VECTO-4.0.3 | Order-Nr 28202896 | HEV P1 Error Mercedes-Benz and Setra Hybrid Buses
- CodeEU-526: VTP calculation aborted on fuel consumption map
- CodeEU-502: Error in VECTO calculation WMA10CZZ0RF022326
- CodeEU-401: Electric steering system with conventional vehicle not according to 2017/2400
- CodeEU-476: Setting Initial SoC in REESS editor leads to error
- CodeEU-533: Question about heavy lorry_IEPC_Gb×4speed: Failed to generate electric power map - at least two negative entries are required
- CodeEU-456: Clarification Documentation official Results
- CodeEU-506: Article 10(2) issue - VIN YS2P6X200R2201285
- CodeEU-507: Article 10(2) issue - VIN YS2P6X20005732399
- CodeEU-508: Article 10(2) issue - VIN S2P6X20005734199
- CodeEU-499: Object Reference not set Error
- CodeEU-546: Problem with P181 (Cooling Fan Technology) for a conventional vehicle
- CodeEU-516: Article10-2-issue | VECTO-4.0.3 | Order-Nr 28208044 | HEV P1 Error Mercedes-Benz and Setra Hybrid Buses
- CodeEU-517: Article10-2-issue | VECTO-4.0.3 | Order-Nr 28208037 | HEV P1 Error Mercedes-Benz and Setra Hybrid Buses

Vecto 4.1.0.3392 RELEASE CANDIDATE

15.04.2024

- **Bugfixes (4/4)**

- CodeEU-519: Article10-2-issue | VECTO-4.0.3 | Order-Nr 10098181 | HEV P1 Error Mercedes-Benz and Setra Hybrid Buses
- CodeEU-527: Article10-2-issue | VECTO-4.0.3 | Order-Nr 28196233 | HEV P1 Error Mercedes-Benz and Setra Hybrid Buses
- CodeEU-528: Article10-2-issue | VECTO-4.0.3 | Order-Nr 28196652 | HEV P1 Error Mercedes-Benz and Setra Hybrid Buses
- CodeEU-338: Eco-roll only, without engine stop, impact on CO2 emission
- CodeEU-475: XML files loading in VTP Job not OK; No auxiliary data and torque curve visible, Job can't be saved in VECTO 4.0.3.3330
- CodeEU-610: VTP mode is broken due to changes in the Clutch component.

Vecto 4.0.3.3330 OFFICIAL RELEASE

13.02.2024

- **Bugfixes**

- CodeEU-293: DistanceRun got an unexpected response
- CodeEU-298: Object reference not set to an instance of an object
- CodeEU-300: Full drive torque miscalculation
- CodeEU-336: Feature: Hashing tool must validate the previous step data for multi-step jobs
- CodeEU-337: Electric Citybus - ERROR with "31a-Specific" bus configuration
- CodeEU-343: Cannot simulate Primary Vehicle using vectocmd.exe
- CodeEU-387: VECTO sometimes fails to properly read Tyre data from primary vehicle xml
- CodeEU-427: Vehicle speed resulting to exceeding max gearbox speed
- CodeEU-428: Remove speed safety margin for gearbox re-engaging
- CodeEU-438: Mismatch XML schema vs Regulation (exempted vehicles)
- CodeEU-248: Bus P2 hybrid VECTO error in urban cycle
- CodeEU-278: Simulation crash when writing fuel consumption results to reports
- CodeEU-284: New error message and failed simulation obtained for P2 hybrid buses
- CodeEU-285: PEV vehicle error in routine to write the results with new vecto version 4.0.2.3275
- CodeEU-287: PEV_IEPC error message:"can only operate on SI Objects with the same unit"
- CodeEU-289: VECTO Simulation Error for bus with validated input data

Vecto 4.0.2.3275 OFFICIAL RELEASE

20.12.2023

- **Hotfix**

- CodeEU-273, CodeEU-274: Changes in the AMT shift strategy regarding idling speed caused simulation aborts
- CodeEU-260: regression fix handling overload buffer

Vecto 4.0.2.3273 OFFICIAL RELEASE

18.12.2023

• Bugfixes (1/2)

- CodeEU-94: DistanceRun got an unexpected response
- CodeEU-153: DrivingActionAccelerate: Failed to find operating point after Overload
- CodeEU-158: Urban RefLoad DrivingActionAccelerate: Failed to find operating point (IEPC Wheelhub 1 measured)
- CodeEU-168: Vecto Declaration Simulation with P1-Hybrid shows multiple errors - Simulation Aborts!
- CodeEU-191: Boosting limits HEV ovc are not working
- CodeEU-202: EMS Standard Values: Continuous/Overload Torque 0 Nm
- CodeEU-203: HybridStrategy error for IHPC type 1 hybrid lorry
- CodeEU-206: VTP + PEMS test done by Renault Trucks France - VECTO tool errors most probably linked to automatic gearbox (with torque converter)
- CodeEU-211: Hybrid P1 configurations with errors
- CodeEU-215: MultiStep tool help
- CodeEU-216: NrOfGears in CIF is 1 for IEPC no matter how many gears it has
- CodeEU-220: Error manual transmission 2. gear
- CodeEU-224: Issue with PEV complete vehicle simulation (Vecto MultiStage)
- CodeEU-231: IVECO CONFIDENTIAL : hybrid buses completed simulation aborted
- CodeEU-234: Error Conventional Lorry Gear: 1C DistanceRun got an unexpected response
- CodeEU-235: Tyre error calculation buses "invalid xsi:type 'TyreDataDeclarationType'"
- CodeEU-238: Bus VIF files not valid in Multistep VECTO
- CodeEU-243: Simulation aborted: Gear 5 Lossmap not sufficient
- CodeEU-244: Signature validation fails for old (prior to v4) Manufacturer reports

Vecto 4.0.2.3273 OFFICIAL RELEASE

18.12.2023

- **Bugfixes (2/2)**

- CodeEU-249: Fix handling gear torque limits in case of IEPC WheelHub motor and only one side is measured
- CodeEU-250: Maximum vehicle speed exceeded during pre-processing
- CodeEU-253: Replace VTP HeavyBus in Generic Vehicles with VTP Truck
- CodeEU-259: Inconsistent calculation of AverageRRC in CIF
- CodeEU-260: Handling of overload buffer in case Continuous Torque is 0Nm
- CodeEU-261: SuperCap internal resistance standard values correction
- CodeEU-263: Determination of rated power for IEPCs for MRF and CIF
- CodeEU-266: Fix Measured Speed Testcases

Vecto 4.0.1.3217 OFFICIAL RELEASE

23.10.2023

- **Improvements**
 - VTP mode: create zip archive for input and output files
- **- Bugfixes**
 - bugfix in CIF for complete(d) buses - do not write PrimaryVehicleSubgroup element
 - fix hybrid strategy: power comparison
 - fix exempted vehicles do not work (error message that XML version is not supported)
 - bugfix in XML schema: remove wrong PS technology entry for lorries
 - bugfix for conditioning power demand for IHPC vehicles

VECTO 4.0.0.3210

16.10.2023



Release Notes

First official VECTO release for the 2nd Amendment of Regulation (EU) 2017/2400

TUG

Features

- Declaration Mode
 - xEV-Heavy Lorries
 - Conventional Medium Lorries
 - xEV Medium Lorries
 - Conventional Buses
 - xEV Buses
- Dedicated user interface for simulating buses in Declaration Mode using the multistep approach: VECTOMultistep.exe
- Engineering Mode
 - xEV-Vehicles
- Updated XML-Reports and Vehicle Information Files to support new Vehicle Architectures
 - New Manufacturer Record File (MRF):
 - New Customer Information File (CIF):
 - Multistep Output (VIF):
- Updated simulation output (.vsum, .vmod)
- Updated Hashing Tool to handle new powertrain components (electric motor, battery, supercap ...)
- Supports .NET Framework 4.8 and .NET 6.0

Features – Tool modes

	Medium Lorries (XML)	Heavy Lorries (XML)	Primary buses (XML)	Interim buses (GUI)	Interim buses (XML)	Completed buses (JSON v7)	Completed buses (GUI)	Completed buses (XML)	Complete buses (JSON v10)	Complete buses (XML)
VECTO.exe	X	X	X			X		X	X	X
VECTOcmd.exe	X	X	X			X		X	X	X
VECTOMultistep.exe	X	X	X	X	X	X	X	X	X	X
Comments				function: generates updated VIF					"Single step" manufacturing process	

X ... Simulation only
X ... Simulation and editing

Changes

- XML Job Files < v2.4 are no longer supported
- Dropped support for .NET Framework 4.5 (EOL 04/2022)

Implementation of Declaration Mode for xEV-Vehicles

- Generic auxiliary parametrisation
- Generic parametrisation of usable SOC range
- Generic parametrisation of Serial/Parallel Hybrid Strategy parameters
- Automated simulation of OVC-HEV
 - Charge depleting mode (CD): The propulsion energy is provided by the electric storage only
 - Charge sustaining mode (CS): The propulsion energy is provided by the fuel storage

Implementation of Declaration Mode for xEV-Lorries

- Generic E-PTO for PEV and S-HEV in Declaration Mode
- E-PTO for PEV and S-HEV in Engineering Mode

Implementation of Declaration Mode for Buses

- Factor Method for conventional and xEV-Buses
- Updated bus auxiliary model