

Sikorsky
 6900 Main Street - P.O. Box 9729
 Stratford, Connecticut 06497-9129



Date: 8 January 2018
 To: Thai Aviation Services Limited
 Attention: Grant Robinson
 Regarding: S-76D Forward Engine Mount Fitting Damage Limits/Repair
 Technical Case #: C0078169

Grant Robinson,

For the 76305-77508-045/046, the wear limit for the outboard link attachment area is a 0.015" or a minimum lug thickness of 0.265". For the 76305-77510-042, the limit of wear for the clevis lug thickness is a 0.110" minimum for lugs (original lug thickness was .120/.130" at 4 locations). This limit is acceptable for all four lugs simultaneously.

Regards,
 Kenneth Welch

Very truly yours,
 SIKORSKY AIRCRAFT CORPORATION

Kenneth Welch
 Service Engineering (Airframe)
 Sikorsky Aircraft Corporation
 124 Quarry Rd.
 Trumbull, Ct 06611-0868
 T: +1(203)416-4052
Kenneth.Welch@sikorsky.com

NOTICES

THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE, REPAIR OR OVERHAUL BY THE RECIPIENT WITHOUT THE WRITTEN CONSENT OF SIKORSKY AIRCRAFT CORPORATION, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED THEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES.

THIS DOCUMENT PROVIDES DISCRETE DISPOSITION AND/OR REPAIR INSTRUCTIONS UNIQUE TO THE SERIALIZED PART OR SERIALIZED AIRCRAFT SPECIFIED HEREIN AND SHALL NOT BE USED FOR DISPOSITION OF SIMILAR CONDITIONS OR REFERENCED AS THE BASIS OF SUBSTANTIATION IN WHOLE OR IN PART, FOR OTHER FORMS OF APPROVED TECHNICAL DATA. THIS DOCUMENT ONLY PROVIDES DISPOSITION FOR CONDITIONS EXPLICITLY IDENTIFIED HEREIN AND DOES NOT CONSTITUTE ABSOLUTE AND FINAL ACCEPTANCE.

EXPORT WARNING

THIS DOCUMENT MAY CONTAIN EXPORT CONTROLLED TECHNICAL DATA, BUT HAS NOT BEEN CLASSIFIED FOR EXPORT PURPOSES.
 DO NOT TRANSFER OR RE-TRANSFER WITHOUT PROPER EXPORT CLASSIFICATION, MARKING, AND SIKORSKY APPROVAL.