

Thanakom Panyothin

From: McConnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Friday, August 31, 2018 4:57 PM
To: Thanakom Panyothin
Cc: Jay Minor; Grant Robinson
Subject: S-76D MGB Oil Cooler Duct Sleeve Bond

Khun San

Following is the CSE response to a request by Jay to bond the S-76D oil cooler duct sleeve using DAPCO 3300.

Case Number: C0103036
Customer: Thai Aviation Services Limited
Aircraft S/N: 761000
Aircraft Model: S-76D
ATA: 63
Part Number: 76302-77812-105
Case Subject: MGB Oil Cooler Duct Sleeve Bond Procedure-Request For

Problem Description:

Reference

- 1) S-76D IPC 63-22-00 IT 55
- 2) Dwg 76302-77812

During a scheduled maintenance inspection on A/C S/N 761059 maintainers noted that the transmission oil cooler sleeve P/N 76302-77812-104 had become disbonded from the P/N -105 duct assembly.

Reference to the AMM showed that there is no procedure to remove, replace or bond the -104 sleeve.

The -105 duct assembly is called out in IPC CH 63-22-00, Fig. 1, Item 55, but the -104 sleeve by itself is not.

Examination of transmission oil cooler duct drawing 76302-77812 found that although Note 22 states that the -104 sleeve is bonded to duct -102 and -105, there is no bond procedure specified.

TAS propose to bond the -104 sleeve to the duct using DAPCO 3300 sealant.

Please advise if the use of DAPCO 3300 is acceptable. If not, please provide an alternate procedure. EoM

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

Problem Resolution:

Per the vendor, Senior Aerospace BWT:

DAPCO 3300 a clear silicone based adhesive, cures at room temperature and should be suitable as it can be used on aircraft because it is resistant to jet fuel and extreme temperatures. It can be used on many surfaces to create a strong, resilient bonds to a variety of substrates.

This email notification is provided as the case has been reviewed and does not contain technical data in the resolution.

David P. McConnell
Senior Field Service Representative

Sikorsky, a Lockheed Martin company
Email dave.p.mcconnell@lmco.com
Smartphone +1 (203) 873-8552 (US)
Efax +1 (860) 998-8791 (US)
Cell +66 (0)8 7750-7920 (Thailand)



WARNING: THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.