

## **Grant Robinson**

---

**From:** McConnell, DAVE P <dave.p.mcconnell@lmco.com>  
**Sent:** Sunday, April 29, 2018 8:03 PM  
**To:** Grant Robinson  
**Cc:** Atiporn Chiwcharoen; Mrazik, Philip  
**Subject:** S-92 MRS Support Bracket Alternate P/N

**Importance:** High

Grant

Provided for your reference. A SoundOff may be appropriate.

Case Number: C0093594  
Customer: Thai Aviation Services Limited  
Aircraft S/N: 920146  
Aircraft Model: S-92A  
Aircraft TT: 6,149  
Case Subject: MRS Support Bracket-Request For P/N Effectivity Confirmation

### **Problem Description:**

Reference  
1) C0093233  
2) C0093395

TAS are replacing the 5-pack installed on A/C S/N 920146 due to metal generation in excess of allowable limits. Case C0093233 refers.

When removing the main rotor servos maintainers found two MRS support brackets to be worn beyond limits.

SCI has no stock of P/N 92351-35302-045 or -047 MRS support brackets.

The response to Case C0093395 indicates that MRS support bracket P/N 92351-15302-043 is also approved for installation in place of the 92351-35302-series brackets.

This is to request confirmation on an AOG basis that MRS bracket P/N 92351-15302-043 is approved for installation on A/C S/N 920146. EoM

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

### **Problem Resolution:**

Sikorsky Service Engineering has reviewed the Engineering documentations, Main Rotor Servo Support Bracket P/N 92351-15302-043 is interchangeable with P/N 92351-35302-045 and P/N

92351-35302-047, and is approved for installation on A/C S/N 920146

This email notification is provided as the case has been reviewed and does not contain technical data in the resolution.

**David P. McConnell**

Senior Field Service Representative  
Sikorsky, a Lockheed Martin company  
Email [dave.p.mcconnell@lmco.com](mailto:dave.p.mcconnell@lmco.com)  
Smartphone +1 (203) 873-8552 (US)  
Efax +1 (860) 998-8791 (US)  
Cell +66 (0)8 7750-7920 (Thailand)



**WARNING:** THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.