

Grant Robinson

From: McConnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Wednesday, February 15, 2017 8:58 PM
To: Daryl Dixon
Cc: Grant Robinson
Subject: 761066 - Request For Ferry Flight

Daryl;

Following is the CSE approval for a UTP-NST ferry flight for 760166.

Case Number: C0053271
Customer: Thai Aviation Services Limited
Aircraft S/N: 761066
Aircraft Model: S-76D
Aircraft TT: 19
Part Number: 76203-02007-043
Case Subject: Ferry Flight-Request For SA No Technical Objection

Problem Description:

Reference Case C0052808.

During loadout at Stewart airport in Newburgh, NY after delivery from SGH to TAS, personnel at Stewart removing the AFDS float switches and switch guards reported discovering bending / deformation of the P/N BHL/S76.3538.001 AFDS switch guard and puncture damage of the P/N 76203-02007 honeycomb panel lower skin at approximately STA 271 underneath the switch guard.

The loadout was completed as planned. Case C0052808 was submitted to obtain a repair scheme for the noted damage.

Upon arrival into Thailand the A/C will be transported by truck to TAS's satellite base at U Tapao airport (VTBU), where it will be reassembled and flown to TAS's main base at Nakhon Si Thammarat (VTSF).

The response to Case C0052808 provided a repair scheme involving replacement of the damaged honeycomb and the addition of a repair doubler on the 76203-02007 panel.

TAS notes that their satellite base at U Tapao is not well equipped or staffed to support this kind of repair work, whereas the main base at Nakhon Si Thammarat is.

TAS request a Sikorsky no objection for a one-time ferry flight of 761066 from U Tapao to Nakhon Si Thammarat. Expected flight duration is estimated to be 2.5 hours. EoM

Problem Resolution:

Ensure the switch guards are securely fastened, and the AFDS system is active prior to ferry flight from U Tapao to Nakhon Si Thammarat for repair.

David P. McConnell

Senior Field Service Representative
Sikorsky, a Lockheed Martin company
Email dave.p.mcconnell@lmco.com
Smartphone +1 (203) 873-8552 (US)
Efax +1 (860) 998-8791 (US)
Cell +66 (0)8 7750-7920 (Thailand)



WARNING: THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.