

Grant Robinson

From: McConnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Thursday, December 29, 2016 3:23 PM
To: Daryl Balmer
Cc: Grant Robinson
Subject: FW: S-92 Static Wick Alternate Part Numbers

From: McConnell, David P SIK
Sent: Tuesday, July 8, 2014 17:49
To: Daryl Dixon <daryl_d@tasl.co.th>
Subject: S-92 Static Wick Alternate Part Numbers

Daryl;

Following is the CSE response to my request for clarification of static wick alternate part numbers. This FTR response can be used as a basis to request HSI shelf stock the P/N 10-900-23 dischargers as an alternate for the P/N 92205-07801-109 discharger.

Log Number:	68651
FTR Number:	10614T113
FTR Date:	Jul 8 2014 3:57AM
Operator:	Thai Aviation Services (CHC)
Aircraft S/N:	920XXX
Aircraft Model:	S-92A
Part ID:	92205-07801
Part Serial #:	N/A
CSE:	Capella
ATA:	55
Ref Docs:	1) AMM Task 55-13-01-960-001 2) Dwg 92205-07801 P/L
FTR Subject:	Static Discharger Alternate P/Ns

Problem Description:

Reference AMM Task 55-13-01-960-001 - Replacement of Static Discharger Wick

Static Discharger assembly P/N 92205-07801-041 uses a P/N 92205-07801-103 discharger.

HSI shows discharger P/N 2-15SCY as an alternate to P/N 92205-07801-103. Static Discharger Dwg 92205-07801 P/L confirms the relationship. This relationship is not shown in the AMM.

Static Discharger assembly P/N 92205-07801-043 uses a P/N 92205-07801-109 discharger, with no alternate P/N shown in the AMM or on the HSI website.

Reference to the Dwg 92205-07801 P/L shows that P/N 10-900-23 is an alternate for 92205-07801-109.

Please confirm the following:

1. Discharger P/N 2-15SCY is an alternate for P/N 92205-07801-103.
2. Discharger P/N 10-900-23 is an alternate for P/N 92205-07801-109.

If these relationships can be confirmed it is recommended that HSI add discharger P/N 10-900-23 to their inventory as an alternate for P/N 92205-07801-109.

This office will submit a SoundOff based on the response to this FTR. EoM

Problem Resolution:

A check of the drawing confirms that:

1. Discharger P/N 2-15SCY is an alternate for P/N 92205-07801-103.
2. Discharger P/N 10-900-23 is an alternate for P/N 92205-07801-109.

Please do not hesitate to contact this office should further information be required.

David P. McConnell

Senior Field Service Representative
Sikorsky Aerospace Maintenance

BlackBerry +1 (203) 873-8552 (US)
Efax +1 (860) 998-8791 (US)
Cell +66 (0)8 7750-7920 (Thailand)