

## **Thanakom Panyothin**

---

**From:** McConnell, DAVE P <dave.p.mcconnell@lmco.com>  
**Sent:** Thursday, October 18, 2018 10:14 PM  
**To:** Daryl Dixon  
**Cc:** Thanakom Panyothin; Grant Robinson  
**Subject:** S-92A Interior Placard  
**Attachments:** S92 Placard Response-18-10-11.pdf  
  
**Importance:** High

Daryl

Per your request.

Case Number: C0107606  
Customer: Thai Aviation Services Limited  
Aircraft S/N: 920000  
Aircraft Model: S-92A  
ATA: 11  
Part Number: STD-220-035-197  
Case Subject: S-92A Interior Placard Legend

### **Problem Description:**

Reference

- 1) AMM Chapter 5
- 2) ICA SIC920003 S-92A Offshore Interior Maintenance Manual
- 3) Attached TAS presentation to CAAT 11 OCT 2018

TAS reports an audit finding raised by the Civil Aviation Authority of Thailand (CAAT) regarding S-92A interior placard P/N STD-220-035-197 that states in part "Life vests stored under seat".

The CAAT finding noted that the placard is incorrect because TAS passengers wear life vests issued by TAS at the time of embarkation and that no vests are stored under the seat.

This finding effects TAS S-92A aircraft S/Ns 920146 and 920279 fitted with optional utility interior installed per Sikorsky Option Code 60000 and covered by S-92A AMM Chapter 5 and ICA SIC920003.

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

### **Problem Resolution:**

Service Engineering states:

This office has reviewed the information provided to CAAT by Thai Aviation Services Ltd. on 11 Oct 2018 and confirms it is current and Approved Data, furthermore we reaffirm there are no alternate placards currently approved for installation in the subject locations in the S92A.

This email notification is provided as the case has been reviewed and does not contain technical data in the resolution.

### **David P. McConnell**

Senior Field Service Representative  
Sikorsky, a Lockheed Martin company  
Email [dave.p.mcconnell@lmco.com](mailto:dave.p.mcconnell@lmco.com)

Smartphone +1 (203) 873-8552 (US)  
Efax +1 (860) 998-8791 (US)  
Cell +66 (0)8 7750-7920 (Thailand)



**WARNING:** THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.