

Grant Robinson

From: McConnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Wednesday, October 18, 2017 9:06 AM
To: Atiporn Chiwcharoen; Grant Robinson
Cc: Mrazik, Philip
Subject: RE: 92500-02101-101 and SS2942-120

Pik

Please see the response to my FTR below.

Dave

Case Number: C0072074
Customer: Thai Aviation Services Limited
Aircraft S/N: 920XXX
Aircraft Model: S-92A
ATA: 54
Part Number: 92500-02101-101
Case Subject: MGB Drip Pan Seal Alt P/N

Problem Description:

TAS ordered MGB drip pan bulbed seal P/N 92500-02101-101.

SCI provided seal P/N SS2942-120 ILO P/N 92500-02101-101 with no substantiation to show that it is an approved alternate or replacement P/N.

The P/L for 92500-02101 shows P/N 92500-02101-101 is made from SS2942-113.

Please confirm that seal P/N SS2942-120 is an alternate, superseding or replacement P/N for 92500-02101-101. EoM

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

Problem Resolution:

SS2942-XXX has the same material specification as 92500-02101-101 and can be used in place of it. The - XXX is the Seal length only and during installation may require trimming.

This email notification is provided as the case has been reviewed and does not contain technical data in the resolution.

From: Atiporn Chiwcharoen [mailto:Atiporn_c@tasl.co.th]
Sent: Tuesday, October 17, 2017 16:47
To: McConnell, DAVE P (TH) <dave.p.mcconnell@lmco.com>; Grant Robinson <Grant_r@tasl.co.th>
Cc: Mrazik, Philip (TH) <philip.mrazik@lmco.com>
Subject: EXTERNAL: RE: 92500-02101-101 and SS2942-120

Thank you Khun Dave.

Best Regards,
Pik
Production Support

Office: +66 (0) 75-809010 Ext. 4320
Mobile: + 66 (0)84-645-2236

From: McConnell, DAVE P [mailto:dave.p.mcconnell@lmco.com]
Sent: Tuesday, October 17, 2017 4:44 PM
To: Atiporn Chiwcharoen; Grant Robinson
Cc: Mrazik, Philip
Subject: RE: 92500-02101-101 and SS2942-120

Pik

I've got nothing in my files proving a 92500-02101-101 / SS2942-120 relationship. I've submitted FTR C0072074 requesting clarification.

I'll let you know when I get a response.

Dave

From: Atiporn Chiwcharoen [mailto:Atiporn_c@tasl.co.th]
Sent: Tuesday, October 17, 2017 15:44
To: Grant Robinson <Grant_r@tasl.co.th>; McConnell, DAVE P (TH) <dave.p.mcconnell@lmco.com>
Subject: EXTERNAL: 92500-02101-101 and SS2942-120

Hi K.Grant/Dave,

Are part# 92500-02101-101 and SS2942-120, Seal interchangeable?

We received part# SS2942-120 as ILO with 92500-02101-101 from SCI? Please see below

B	HELIICOPTER SUPPORT, INC	Airline/Freight Forwarder	INVOICE/PACKING LIST:	53011
I	TOTAL POWER ASSURANCE	Port of Export	INVOICE DATE:	02/20
L	124 QUARRY ROAD	Validated Export License No. Expiration Date	DATE SHIPPED:	02/20
L	TRUMBULL, CT 06611	NLR	MASTER SHIPPER:	11011
T		Via	INCOTERMS:	FCA
O		FED-EX, P1 PPD	CUSTOMER PAYMENT TERMS:	NO C
S	Thai Aviation Services Limited	Tracking Numbers		
H	121/51, RS Tower Building	797986727431		
I	12th Floor			
P	Ratchadaphisek Road			
T	Dindeang, Dindeang, Bangkok			
O	10400 Thailand			
Item	Part Number	Description	PO Number	UM
2	SS2942-120	SEAL	BKKFO-14-008	Each
		U.S. Commerce Department (EAR) designation, ECCN Number 9A991D refers. FAA Form 8130-3 is included. Value for Customs: \$158.12		New
		ILO 92500-02101-101		1
2	SS2942-120	SEAL	BKKFO-14-008	Each
		U.S. Commerce Department (EAR) designation, ECCN Number 9A991D refers. FAA Form 8130-3 is included. Value for Customs: \$158.12		New
		ILO 92500-02101-101		1
1	4091T51P01	SEAL	BKKFO-14-024	Each
		U.S. Commerce Department (EAR) designation, ECCN Number 9A991C refers. FAA Form 8130-3 is included. Value for Customs: \$3,955.70		New
1	4091T51P01	SEAL	BKKFO-14-024	Each
		U.S. Commerce Department (EAR) designation, ECCN Number 9A991C refers. FAA Form 8130-3 is included. Value for Customs: \$3,955.70		New

Best Regards,

Pik

Production Support

Office: +66 (0) 75-809010 Ext. 4320

Mobile: + 66 (0)84-645-2236

TAS web portal : <http://saas.tasl.co.th>

*The information contained in this message is confidential and is intended for the addressee only.
If you have received this message in error or there are any problems please notify the originator
immediately.*

The unauthorised use, disclosure, copying or alteration of this message is strictly forbidden.

TAS web portal : <http://saas.tasl.co.th>

*The information contained in this message is confidential and is intended for the addressee only.
If you have received this message in error or there are any problems please notify the originator
immediately.*

The unauthorised use, disclosure, copying or alteration of this message is strictly forbidden.