

Thanakom Panyothin

From: McConnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Thursday, July 26, 2018 6:05 PM
To: Thanakom Panyothin
Cc: Grant Robinson; Atiporn Chiwcharoen; Mrazik, Philip; Daryl Dixon
Subject: S-76D Duct flange crack repair

Importance: High

Khun San

Following is the CSE approval to my request to temporarily repair exhaust duct flanges by stop drilling and monitoring.

Case Number: C0100352
Customer: Thai Aviation Services Limited
Aircraft S/N: 761000
Aircraft Model: S-76D
ATA: 78
Part Number: 76308-77003 / 76308-77004
Case Subject: Exhaust Duct Flange Crack-Request To Stop Drill And Monitor

Problem Description:

On 25 JUL 2018 TAS maintainers performing scheduled maintenance inspections on the S-76D fleet found five exhaust ducts with flange lobe cracks of varying levels of severity.

Qty 02 L/H FWD ducts P/N 76308-77003-041 Post CSN 76-262

Qty 01 R/H FWD duct P/N 76308-77003-042 Post CSN 76-262

Qty 01 L/H AFT duct P/N 76308-77004-043

Qty 01 R/H AFT duct P/N 76308-77004-044

Reference attached JPEG images of the worst-case FWD and AFT ducts.

All cracks occurred on the flanges and typically run around the attach bolt hole. No branching or missing pieces was observed.

This finding has grounded two or the five TAS A/C. TAS has no serviceable exhaust ducts in stores. SCI has no ducts available and has quoted TAS replacement lead times ranging from 203 to 321 days.

TAS had been sending cracked ducts to an in-country repair facility, but the last four ducts that were returned with flange doublers added per AMM Task 78-10-01-300-802 had to be scrapped for being out-of-round. It is not known if the repair facility has developed a process problem, or if ducts having multiple repairs already applied should be fixtured during the welding process.

In order to avoid significant AOG time for two-fifths of the fleet, TAS request SA approval to stop drill and monitor as many of the ducts as possible, and to keep the ducts in service with periodic inspections until such time as the cracks propagate past the stop drill holes, or until receipt of spares, whichever occurs first.
EoM

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

Problem Resolution:

To continue use, stop drill both ends of existing cracks (using the SRM for guidance). Inspect for growth past the stop drill and monitor the adjacent lobes for cracking – daily. If further cracking is noted, contact Sikorsky for further guidance. Replace when spares are available.

This email notification is provided as the case has been reviewed and does not contain technical data in the resolution.

David P. McConnell

Senior Field Service Representative
Sikorsky, a Lockheed Martin company
Email dave.p.mcconnell@lmco.com
Smartphone +1 (203) 873-8552 (US)
Efax +1 (860) 998-8791 (US)
Cell +66 (0)8 7750-7920 (Thailand)



WARNING: THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.