

## Grant Robinson

---

**From:** McConnell, DAVE P <dave.p.mcconnell@lmco.com>  
**Sent:** Tuesday, January 10, 2017 1:14 PM  
**To:** Russell Squires  
**Cc:** Grant Robinson  
**Subject:** AMM T-Rev 5-184 Raft Overhaul

Russ;

Following is the CSE response to my request for clarification of the raft overhaul interval in T-Rev 5184.

My apologies for my tardy response.

Case Number: C0047224  
Customer: Thai Aviation Services Limited  
Aircraft S/N: 920279  
Aircraft Model: S-92A  
ATA: 25  
Part Number: 92850-08801-series  
Case Subject: T-Rev 5-184 Raft O/H Interval-Request For Clarification

**Problem Description:**

TAS maintainers reviewing AWL T-Rev 5-184 note that Task 25-61-03-780-001 calls out life raft overhaul at 24 or 12 months.

They further note that the same Task 25-61-03-780-001 called out in 5-23-00-200-001 – Component scheduled Maintenance Checks – still shows only a 12-month interval.

Please confirm that the 12-month callout in Task 5-23-00-200-001 is no longer correct, and that it should actually be 24 or 12 months as per T-Rev 5-184 Task 25-61-03-780-001. EoM

**Problem Resolution:**

T-Rev 5-184 only revised the Rescue Hoist overhaul requirements, not the Life Raft Inspection requirement.

As the entry in the current overhaul table states, this inspection requirement was moved to the Component Scheduled Maintenance Checks, 5-23-00. The 24 Month/12 Month requirement in 5-10-00 is not applicable.

Per the Component Scheduled Maintenance Checks, 5-23-00, Life Raft inspection is performed every 12 months from date the raft is put into service on the aircraft IAW task 25-61-03-780-001.

The task 25-61-03-780-001 allows for an initial one-time extension of the raft inspection to 24 months from the date of manufacture of the raft provided it has not been installed on the aircraft.

Inspection interval of an in service life raft is every 12 months.

**David P. McConnell**  
Senior Field Service Representative  
Sikorsky, a Lockheed Martin company  
Email [dave.p.mcconnell@lmco.com](mailto:dave.p.mcconnell@lmco.com)  
Smartphone +1 (203) 873-8552 (US)  
Efax +1 (860) 998-8791 (US)  
Cell +66 (0)8 7750-7920 (Thailand)



**WARNING:** THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.