

Grant Robinson

From: McConnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Friday, December 09, 2016 9:32 AM
To: Grant Robinson
Subject: HVE flame detector return for engineering evaluation
Attachments: SA1600-Flame Detector SN 4822.pdf

Grant;

Per the FTR response below, engineering is requesting the return of the flame detector removed from HVE for failure to test. A completed SA1600 form is attached.

Case Number: C0047913
Customer: Thai Aviation Services Limited
Aircraft S/N: 761063
Aircraft Model: S-76D
Aircraft TT: 42
ATA: 26
Part Number: 76306-07902-104
Case Subject: 90-Day Delivery-Low Time Fail-Flame Detector Failed Test

Problem Description:

90 Day Delivery Discrepancy-Low Time Failure

The No. 1 flame detector system failed to test during a pre-takeoff check of the engine fire detection system.

Troubleshooters confirmed that the No. 1 forward flame detector was inoperative.

The flame detector was replaced with a serviceable component purchased from Heli-One.

P/N 76306-07902-104
S/N off 4822 Component TSN 41.5
S/N on 4738

Please advise if the removed flame detector is required for engineering evaluation. EoM

Problem Resolution:

Sikorsky engineering DOES want this flame detector for engineering evaluation. Please fill out the SA1600 form with Robert Andrejczyk as the engineering POC.

David P. McConnell

Senior Field Service Representative
Sikorsky, a Lockheed Martin company
Email dave.p.mcconnell@lmco.com
Smartphone +1 (203) 873-8552 (US)
Efax +1 (860) 998-8791 (US)
Cell +66 (0)8 7750-7920 (Thailand)



WARNING: THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR

SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.