

Grant Robinson

From: McConnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Friday, August 24, 2018 9:52 AM
To: Grant Robinson
Cc: Thanakom Panyothin
Subject: RE: S76D Exhaust Duct Part Numbers 047/048

Importance: High

Grant

Following is the CSE response confirming that the -047 and -048 forward exhaust ducts appear on production drawing 76308-77000, and are eligible for installation on post CSN 76-262 aircraft.

Case Number: C0102925
Customer: Thai Aviation Services Limited
Aircraft S/N: 761000
Aircraft Model: S-76D
ATA: 78
Part Number: 76308-77003-047 / -048
Case Subject: Forward Exhaust Duct-Request For P/N Applicability Confirmation

Problem Description:

Reference

- 1) S-76D IPC CH 78-10-01
- 2) T-Rev 78-07

The S-76 D IPC Numerical Index lists forward exhaust duct P/Ns 76308-77003-047 and -048.

IPC T-Rev 78-07 does not list the -047 and -048 ducts.

TAS has recently received -047 and -048 ducts from SCI but is unable to confirm from IPC data that they are eligible for installation on their A/C. They believe that T-Rev 78-07 is in error.

TAS request confirmation that forward exhaust ducts P/N 76308-77003-047 and -048 are still eligible for installation on A/C that have complied with CSN 76-262. EoM

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

Problem Resolution:

Sikorsky Engineering states that P/N 76308-77003-047/048, are the new P/N's that tree into P/N 76308-77000-013/-014, which shows the CSN 76-262 incorporated.

This email notification is provided as the case has been reviewed and does not contain technical data in the resolution.

David P. McConnell
Senior Field Service Representative
Sikorsky, a Lockheed Martin company

Email dave.p.mcconnell@lmco.com
Smartphone +1 (203) 873-8552 (US)
Efax +1 (860) 998-8791 (US)
Cell +66 (0)8 7750-7920 (Thailand)



WARNING: THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.

From: Grant Robinson <Grant_r@tasl.co.th>
Sent: Wednesday, August 22, 2018 12:15
To: Mcconnell, DAVE P (TH) <dave.p.mcconnell@lmco.com>
Subject: EXTERNAL: S76D Exhaust Duct Part Numbers 047/048

Hi Dave

As discussed, TAS would like to request an FTR clarification on the effectivity of part number 76308-77003-047 and -048 Fwd Exhaust Ducts. The number still exists in the S76D IPC Numerical Index but has been removed, presumably accidentally, by Trev 78-07. The -047/048 ducts are production ducts with CSN 76-262 incorporated. TAS orders the 047/048 but question as to being able to install them as they are not in the IPC have arisen. Sound Off GrRo180729-2226 has been submitted. Thank you.

Best Regards,

Grant Robinson
Repair Station Manager

Thai Aviation Services Ltd.
Nakhon Si Thammarat Base
Mobile: +66 (0)9-2224-5937
Office: +66 (0)75-809-010
Email: grant_r@tasl.co.th
Web: <http://www.tasl.co.th/>



TAS web portal : <http://saas.tasl.co.th>

The information contained in this message is confidential and is intended for the addressee only.

*If you have received this message in error or there are any problems please notify the originator immediately.
The unauthorised use, disclosure, copying or alteration of this message is strictly forbidden.*