

Grant Robinson

From: McConnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Saturday, February 03, 2018 9:26 PM
To: Grant Robinson
Cc: Mrazik, Philip; Atiporn Chiwcharoen
Subject: RE: HS-HVF AOG

Importance: High

Grant

P/N -058 rotor brake accumulator bracket use is approved for TAS D fleet use as per below.

Dave

Case Number: C0086809
Customer: Thai Aviation Services Limited
Aircraft S/N: 761XXX
Model: S-76D
ATA: 63
Part Number: 76650-02001-062
Case Subject: Rotor Brake Accumulator Bracket -058 In Lieu Of -062

Problem Description:

Reference

- 1) Case C0085949
- 2) S-76C IPC CH 66-50-00

Per Case C0085949 TAS reported a cracked P/N 76650-02001-062 rotor brake bracket on A/C S/N 761060.

TAS stop-drilled the bracket. SCI has quoted a lead time of 131 days for a replacement.

TAS now reports finding a similarly cracked bracket on A/C S/N 761063 and a bracket with branching cracks on 761064.

TAS has grounded 761064 as the cracking is too extensive to stop drill.

TAS expects to find further cracks on brackets installed on 761059 and 761066.

Reference to S-76C IPC Chapter 66-50-00 Fig 1, Page 8, Item 58 shows that bracket dash numbers 76650-02001-058 and -062 are approved for use on the C model.

SCI has Qty 23 P/N -058 brackets in stock, as confirmed by TAS's on-site Sikorsky LSR.

This is to request on an AOG basis SA approval to install P/N 76650-02001-058 rotor brake accumulator brackets on S-76D-model A/C in the TAS fleet (D59, D60, D63, D64 and D66) until such time as a -062 bracket for each A/C is received from SCI. EoM

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

From: Grant Robinson [mailto:Grant_r@tasl.co.th]
Sent: Saturday, February 3, 2018 18:40
To: Mcconnell, DAVE P (TH) <dave.p.mcconnell@lmco.com>
Subject: EXTERNAL: Fwd: HS-HVF AOG

Hi Dave

We now have 3 a/c with these cracked. Some serious. I think we need to ask for approval to use the -058 please. HVE and HVF now have cracked also. HVF is multiple so stop drilling is not an option. Thx

Regards,
Grant Robinson
Type Engineer - Sikorsky
Thai Aviation Services (TAS)
Mobile: +66 (0)9 2224-5937

Sent from my iPhone

Begin forwarded message:

From: Nakhon Stores <nakhon-stores@tasl.co.th>
Date: 3 February AD 2018 17:49:39 GMT+7
To: "Mrazik, Philip" <philip.mrazik@lmco.com>, "Mcconnell, DAVE P
(dave.p.mcconnell@lmco.com)" <dave.p.mcconnell@lmco.com>, Atiporn Chiwcharoen
<Atiporn_c@tasl.co.th>
Cc: Grant Robinson <Grant_r@tasl.co.th>, Daryl Dixon <daryl_d@tasl.co.th>, Kriangsak
Hongsuwanwattana <Kriangsak_h@tasl.co.th>, Sineenat Wisitcharoen
<Sineenat_W@tasl.co.th>, Nakhon Supervisor Engineer <nakhon-se@tasl.co.th>, Brent Lomnes
<Brent_1@tasl.co.th>, Nakhon Stores <nakhon-stores@tasl.co.th>
Subject: RE: HS-HVF AOG

Hello Khun Phil,

There is AOG requirement of BRACKET, R/B ACCUMULATOR p/n: 76650-02001-062 for HS-HVF per below detail.
Pls supply the part.

Best Regards;
Tiwa,
Stores Section
Nakhon Si Thammarat (NST)
Tel: +66 75 809010-38 Ext. 4450
E-mail: nakhon-stores@tasl.co.th.

-----Original Message-----

From: Brent Lomnes
Sent: Saturday, February 03, 2018 5:40 PM
To: Nakhon Stores
Subject: HS-HVF AOG

Stores:

TC 180074-33 has been created for HS-HVF - AOG

PN: 76650-02001-062

DESC: BRACKET, R/B ACCUMULATOR

QNTY: 1

AC: SN: 761064

Next scheduled flight: 04 Feb 2017

Defect: Total of five cracks around mounting holes

This are the only part AOG for HVF

Best Regards,

Brent Lomnes

TAS AME

NST Thailand

09-9394-6312

TAS web portal : <http://saas.tasl.co.th>

The information contained in this message is confidential and is intended for the addressee only.
If you have received this message in error or there are any problems please notify the originator immediately.

The unauthorised use, disclosure, copying or alteration of this message is strictly forbidden.

TAS web portal : <http://saas.tasl.co.th>

The information contained in this message is confidential and is intended for the addressee only.
If you have received this message in error or there are any problems please notify the originator immediately.

The unauthorised use, disclosure, copying or alteration of this message is strictly forbidden.

TAS web portal : <http://saas.tasl.co.th>

The information contained in this message is confidential and is intended for the addressee only.

If you have received this message in error or there are any problems please notify the originator immediately.

The unauthorised use, disclosure, copying or alteration of this message is strictly forbidden.