


INSTRUCTIONS

Verification of truth table for FULL ADDER



Reset

TRUTH TABLE						Print
Serial No.	A	B	C _{in}	Sum	C _{out}	Remarks
1	0	0	0	0	0	Correct
2	0	0	1	1	0	Correct
3	0	1	0	1	0	Correct
4	0	1	1	0	1	Correct
5	1	0	0	1	0	Correct
6	1	0	1	0	1	Correct
7	1	1	0	0	1	Correct
8	1	1	1	1	1	Correct