

Fuel Station AI Log Report

Time: 2025-10-30 22:57:11

Log: Compressor overheated during refill

Predicted Category: Mechanical failure

This report was auto-generated by the AI maintenance log analyzer.