

Fuel Station AI Log Report

Time: 2025-11-03 19:39:23

Log: Compressor overheated during refill

Predicted Category: Mechanical failure

Machine Status:

Machine 1: Stopped suddenly

Machine 2: Overheating

Machine 3: Sensor issue

Machine 4: Working normally

Fuel Level: 621 L (12.4% full)

Water in Tank: Yes

This report was auto-generated by the AI maintenance log analyzer.