
Finding Missing Neighbors

Finding Missing Neighbors function helps you to find out detected cells not listed in Neighbor List even with strong signal.

1. Double-click or drag and drop Finding Missing Neighbors under Beceem or DRT Scanner tree.
2. Neighbor List Analysis window appears.



The detailed description of each item in Neighbor List Analysis window is as follows.

Item	Description
Reference Parameter	Select reference parameter. For DRT, apply Reference Parameter set from main Menu bar – Tools – Options – General – DRT Scanner Best Server.
Threshold of CINR/RSSI among Neighbor	CINR/RSSI threshold of neighbor data
Difference with Serving CINR/RSSI	CINR/RSSI differences between serving and neighbor
Consecutive Time duration Satisfied	Time which satisfies the above two conditions

3. Set conditions in Neighbor List Analysis window to find out missing neighbors.
4. Click OK.
5. Missing neighbor parameters are to be added under Finding Missing Neighbors tree.

© Copyright by Accuver Co., Ltd.