

MSP430FR5043 Texas Instrument MCU

Pin No	Description	Connected To
P1.0	5V Monitor	5V_MON
P1.1	3V3 Monitor	3V3_MON
P1.2	12V FAN	FAN1_TACH
P1.3	12V FAN	FAN2_TACH
P1.4	12V FAN	FAN1_PWM
P1.5	12V FAN	FAN2_PWM
P2.0	Debug through FTDI	DEBUG_TX
P2.1	Debug through FTDI	DEBUG_RX
P3.3	Magnetic REED Switch	REED_SWITCH
P3.1	12V FAN TURN ON / OFF	FAN1_EN
P3.4	12V FAN TURN ON/OFF	FAN2_EN
P3.5	SERVO ENABLE	SERVO_EN
P4.3	GAS SENSOR PIN	N2O_TXD
P4.4	GAS SENSOR PIN	N2O_RXD
P5.0	RS485	DI/TXD
P5.1	RS485	RO/RXD
P5.5	I2C SENSOR	SDA
P5.6	I2C SENSOR	SCL
P5.7	5V SERVO MOTOR	SERVO_PWM
P6.0		LED
P6.2		RS485_DE/RE Control Pin
PJ.4/LFXIN	Oscillator	32.768kHz
PJ.5/LFXOUT	Oscillator	32.768Khz
TEST/SBWCLK	Programming	TEST_SBWCLK
RST/NMI/SBWTDIO	Programming	RST_SBWTDIO_N