Problem 1

```
syms t1 a1 t2 a2 d3 d4 t4
% Calculate DH Homogeneous Transformation Matrices for each link
A01 = simplify(DHTransform(t1, 0, 0, a1));
A12 = simplify(DHTransform(t2, 0, pi, a2));
A23 = simplify(DHTransform(0, d3, 0, 0));
A34 = simplify(DHTransform(t4, d4, 0, 0));
% Calculate Homogeneous Transformation Matrices from base frame to end
of
% each link
T01 = simplify(A01);
T02 = simplify(T01*A12);
T03 = simplify(T02*A23);
Te = simplify(T03*A34);
% Extract necessary vectors from Homogeneous transforms to calculcate
the
% Jacobian
z0 = T01(1:3, 3);
z1 = T02(1:3, 3);
z2 = T03(1:3, 3);
z3 = Te(1:3, 3);
P0 = [0, 0, 0]';
P1 = T01(1:3, 4);
P2 = T02(1:3, 4);
P3 = T03(1:3, 4);
Pe = Te(1:3, 4);
% Calculate the Jacobian
J = [cross(z0, Pe-P0), cross(z1, Pe-P1),
                                                    z2, cross(z3, Pe-
P3);
                                      z1, zeros(3, 1),
                    z0,
 z3];
```

Published with MATLAB® R2017b