


BOM CHECK (automated - verify before acting)
- red = on drawing, missing in BOM
- orange = qty / spec / revision mismatch
- yellow = confirm match / extra / duplicate
- blue = suggestion (implied item, rule-based)




Front view
Scale: 1:3




Left view
Scale: 1:3



Top view
Scale: 1:3



Top view
Scale: 1:3




Front view
Scale: 1:3

FITS FOR ASSEMBLY	
TYPES OF FIT TRANSITION FIT	DESIGNATION H7m6 (GEAR AND SHAFT)


SR NO.	PART NAME	QTY.
17	NUT	14
16	BOLT	14
15	RIGHT SIDE CASING	1
14	LEFT SIDE CASING	1
13	OUTPUT SHAFT KEY	1
12	INTERMEDIATE SHAFT KEY	2
11	INPUT SHAFT KEY	1
10	OUTPUT SHAFT BEARING	1
9	INTERMIDIATE SHAFT BEARING	1
8	INPUT SHAFT BEARING	1
7	INTERMEDIATE SHAFT	1
6	OUTPUT SHAFT	1
5	INPUT SHAFT	1
4	SPUR PINION	1
3	SPUR GEAR	1
2	HELICAL PINION	1
1	HELICAL GEAR	1

BILL OF MATERIAL



Isometric view
Scale: 1:3

FIRST ANGLE



ALL MEASUREMENTS ARE IN MM

SINHGAD TECHNICAL EDUCATION SOCIETY'S
RMD SINHGAD SCHOOL OF ENGINEERING, WARJE, PUNE- 411 058.

NAME :			COURSE : ROLL NO :
	DATE	SIGNATURE	REMARK
STARTING			
COMPLETION			
TITLE:			SHEET NO : SCALE :

BOM CHECK SUMMARY

Drawing : 414073292-2.pdf   (Rev ?)
BOM   : economiser_assembly_bom.xlsx   (Rev D)
Input   : vector PDF
RUN RELIABILITY : HIGH

Drawing items checked : 17
BOM lines read   : 17
BOM completeness   : 100.0% (drawing items that have a BOM line)

Findings: none

Automated check - not a substitute for engineering review. Blue items are rule-based suggestions.