

4. LDR

```
const int ledPin = 2;

const int ldrPin = A0;

void setup() {
    Serial.begin(9600);
    pinMode(ledPin, OUTPUT);
    pinMode(ldrPin, INPUT);
}

void loop() {
    int ldrStatus = analogRead(ldrPin);
    if (ldrStatus <= 700) {
        digitalWrite(ledPin, HIGH);
        Serial.print("Its DARK, THE LED is Turned ON : ");
        Serial.println(ldrStatus);
    }
    Else
    {
        digitalWrite(ledPin, LOW);
        Serial.print("Its BRIGHT, The LED is Turned OFF : ");
        Serial.println(ldrStatus);
    }
    delay(500);
}
```