

5.SOIL MOISTURE

```
#define SENSOR_PIN A0
```

```
#define DRY_VALUE 650
```

```
#define WET_VALUE 300
```

```
void setup(){
```

```
    Serial.begin(9600);
```

```
}
```

```
void loop() {
```

```
    int sensorValue = analogRead(SENSOR_PIN);
```

```
    int moisturePercentage = map(sensorValue, DRY_VALUE,WET_VALUE,0, 100);
```

```
    moisturePercentage = constrain(moisturePercentage, 0, 100);
```

```
    Serial.print("Soil Moisture:");
```

```
    Serial.print(moisturePercentage);
```

```
    Serial.print("%");
```

```
    Serial.print(sensorValue);
```

```
    delay(1000);
```

```
}
```