```
% JointCoords_DH.m
% Tarik Tosun, MAE 345, Princeton University
% Created 9/27/11
% Description:
   Function returning the joint coordinates of a kinematic chain given the
્ટ
응
   Denavit-Hartenberg matrices for its joints in their current state.
  DH transformation matrices are passed in as a cell array of 4x3
응
응
   matrices. Returned joint coords vector has coordinates for N+1 joints,
   where N is the number of transformation matrices (the first joint is
응
   the base joint, [0 0 0]).
% Usage;
%
   coords[x1,y1,z1;x2,y2,z2;...] = JointCoords_DH(DH_Mats{[1],[2],...});
응
% Last Edited: 9/27/11
function coords = JointCoords_DH(DH_Mats)
   %check args
   if(~iscell(DH_Mats))
       error('DH_Mats must be a cell array.');
   end
   응응응
   N = size(DH\_Mats, 2);
   coords = zeros(N+1,3);
   xform = eye(4,4);
   for i=1:N
       %generate xform matrix for this joint:
      xform = xform * DH_Mats{i};
       c = xform * [0 0 0 1]';
       coords(i+1,:) = c(1:3)';
   end
end
```