Photos



Photo 1: Standing below diversion looking upstream. August 5, 20091.



Photo 2: Standing in same spot looking downstream. August 5, 2009.



Photo 3: Jump height from pool below structure to top of structure ~ 3.5 feet.



Photo 4: ODFW removing rock to provide passage under check log.



Photo 5: Temporary passage provided under check log (near side of log). This is a temporary solution and not expected to last longer than the summer season. While adult salmonids may be able to negotiate this barrier at higher flow juveniles will have trouble passing above this structure at all flows and times of year.