WORK INSTRUCTION

Document ID: DOC-0001597
Project: PRJ-003
Uploaded on: 2024-12-01
Uploaded by: user156
Export class: EAR99

Assembly of P-101491 at plant PLT04

Part Number: P-101491
Revision: A.1
Plant: PLT04
Station: ST-14
Torque (Nm): 8
Cycle time (s): 254

Step 1: Record result

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Torque to specification

Step 5: Clean mating surface

Step 6: Torque to specification

Step 7: Clean mating surface

Step 8: Apply thread locker