WORK INSTRUCTION

Document ID: DOC-0001635
Project: PRJ-012
Uploaded on: 2024-12-25
Uploaded by: user023
Export class: EAR99

Assembly of P-102335 at plant PLT04

Part Number: P-102335
Revision: A.1
Plant: PLT04
Station: ST-71
Torque (Nm): 8
Cycle time (s): 264

Step 1: Inspect incoming part

Step 2: Record result

Step 3: Clean mating surface

Step 4: Clean mating surface

Step 5: Apply thread locker

Step 6: Apply thread locker