EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0002790
Project: PRJ-012
Uploaded on: 2026-06-24
Uploaded by: user131
Export class: ECCN-3A001

Assembly of P-100759 at plant PLT03

Part Number: P-100759
Revision: A.1
Plant: PLT03
Station: ST-27
Torque (Nm): 12
Cycle time (s): 262

Step 1: Move to next station

Step 2: Apply thread locker

Step 3: Visual check

Step 4: Inspect incoming part

Step 5: Clean mating surface

Step 6: Clean mating surface

Step 7: Inspect incoming part

Step 8: Torque to specification