WORK INSTRUCTION

Document ID: DOC-0002804
Project: PRJ-035
Uploaded on: 2026-06-30
Uploaded by: user199
Export class: EAR99

Assembly of P-102373 at plant PLT04

Part Number: P-102373
Revision: A.1
Plant: PLT04
Station: ST-23
Torque (Nm): 5
Cycle time (s): 277

Step 1: Torque to specification

Step 2: Clean mating surface

Step 3: Apply thread locker

Step 4: Apply thread locker

Step 5: Apply thread locker

Step 6: Fit fasteners

Step 7: Apply thread locker

Step 8: Move to next station

Assembly of P-103804 at plant PLT03

Part Number: P-103804
Revision: A.1
Plant: PLT03
Station: ST-62
Torque (Nm): 2.5
Cycle time (s): 53

Step 1: Record result

Step 2: Move to next station

Step 3: Torque to specification

Step 4: Clean mating surface

Step 5: Visual check

Step 6: Record result

Assembly of P-101847 at plant PLT01

Part Number: P-101847
Revision: A.1
Plant: PLT01
Station: ST-31
Torque (Nm): 5

Cycle time (s): 91

Step 1: Visual check

Step 2: Move to next station

Step 3: Torque to specification

Step 4: Fit fasteners

Step 5: Apply thread locker

Step 6: Fit fasteners

Step 7: Record result

Step 8: Clean mating surface