WORK INSTRUCTION

Document ID: DOC-0001555
Project: PRJ-035
Uploaded on: 2024-11-12
Uploaded by: user119
Export class: EAR99

Assembly of P-101958 at plant PLT02

Part Number: P-101958
Revision: A.1
Plant: PLT02
Station: ST-39
Torque (Nm): 8
Cycle time (s): 39

Step 1: Apply thread locker

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Move to next station