WORK INSTRUCTION

Document ID: DOC-0001235
Project: PRJ-011
Uploaded on: 2024-06-25
Uploaded by: user099
Export class: EAR99

Assembly of P-101212 at plant PLT04

Part Number: P-101212
Revision: A.1
Plant: PLT04
Station: ST-29
Torque (Nm): 12
Cycle time (s): 45

Step 1: Visual check

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Fit fasteners

Step 5: Apply thread locker