WORK INSTRUCTION

Document ID: DOC-0002717
Project: PRJ-033
Uploaded on: 2026-05-23
Uploaded by: user079
Export class: EAR99

Assembly of P-103926 at plant PLT02

Part Number: P-103926
Revision: A.1
Plant: PLT02
Station: ST-99
Torque (Nm): 2.5
Cycle time (s): 48

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Inspect incoming part

Step 4: Record result

Step 5: Visual check

Assembly of P-100254 at plant PLT04

Part Number: P-100254
Revision: A.1
Plant: PLT04
Station: ST-98
Torque (Nm): 8
Cycle time (s): 132

Step 1: Move to next station

Step 2: Fit fasteners

Step 3: Visual check

Step 4: Record result

Step 5: Inspect incoming part

Step 6: Fit fasteners

Assembly of P-101512 at plant PLT03

Part Number: P-101512
Revision: A.1
Plant: PLT03
Station: ST-35
Torque (Nm): 20
Cycle time (s): 154

Step 1: Move to next station

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Move to next station

Step 5: Torque to specification

Step 6: Torque to specification