# WORK INSTRUCTION

**Document ID:** DOC-0000905
**Project:** PRJ-038
**Uploaded on:** 2024-01-25
**Uploaded by:** user054
**Export class:** EAR99

## Assembly of P-100802 at plant PLT04

**Part Number:** P-100802
**Revision:** A.1
**Plant:** PLT04
**Station:** ST-32
**Torque (Nm):** 12
**Cycle time (s):** 283

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Clean mating surface

Step 4: Visual check

Step 5: Apply thread locker

Step 6: Torque to specification